



U.S. Department of Transportation

National Highway Traffic Safety Administration

#### Dear Crash Data Researchers/Users:

Thank you for choosing crash data from the National Highway Traffic Safety Administration (NHTSA) for your research or other use. The information contained in this motor vehicle crash report is collected, maintained and distributed in accordance with Public Law 89-564. In accordance with this Public Law, NHTSA is required not to release any case information until completion of quality control procedures. These procedures include a review of the case material to extract all names, licenses and registration numbers, non-coded interview material, non-research related researcher comments in the margins, non-factual data, and the production number portion of the vehicle identification number (VIN).

If you requested NHTSA to query its database files in order to identify a specific crash, then that query was made using non-personal descriptors you provided for use in our search. This motor vehicle crash may have been identified from a data search and matches the general, non-personal descriptors you provided, but we cannot confirm that this is the specific crash report you requested.

If you have any questions with regard to the above procedures, please contact the Field Operations Branch, Crash Investigation Division, National Center for Statistics and Analysis at 202-366-4820. Again, please be advised that we cannot confirm that this is the case that you have specifically requested nor can we certify the information to be correct.

\*\*\* \*\*\* \*\*\*



UMTRI - 96 - 8 VERSION 05

> UM-3731-98 1998 Chevrolet Camaro

# In-depth Vehicle Occupant Report

The University
of Michigan
Transportation
Research Institute



#### **DISCLAIMERS**

This document is disseminated under the sponsorship of the Department of Transportation in the interest of information exchange. The United States Government assumes no responsibility for the contents or use thereof.

The opinions, findings, and conclusions expressed in this publication are those of the authors and not necessarily those of the National Highway Traffic Safety Administration.

The crash investigation process is an inexact science which requires that physical evidence such as skid marks, vehicular damage measurements, and occupant contact points are coupled with the investigator's expert knowledge and experience of vehicle dynamics and occupant kinematics in order to determine the pre-crash, crash, and post-crash movements of involved vehicles and occupants.

Because each crash is a unique sequence of events, generalized conclusions cannot be made concerning the crashworthiness performance of the involved vehicle(s) or their safety systems.

Case Vehicle (A): 1998 Chevrolet Type: Camaro, 2-door coupe

Driver: 18-year-old male

CDC: 12-FRWN-3, 12-FZEW-1, 00-LDAO-2

#### Situation

(Slide 1) Case vehicle (A) was traveling in the southbound lane of a straight section of a dry, asphalt, three-lane roadway, (slide 2, 3, 4) with a speed limit of 55 mph. The driver of case vehicle (A) reportedly fell asleep at the wheel and case vehicle (A) drifted off of the right shoulder as it approached a three-leg intersection. Case vehicle (A) struck a culvert, and impacted the embankment with its front end and the culvert with its right-front wheel. Case vehicle (A) then vaulted and rolled over 4 quarter turns before coming to rest on its wheels in a cornfield, southwest of the intersection, and facing east.

Using the WinSMASH accident-reconstruction program and (slides 5, 6, 7, 8, 9) c-values for case vehicle (A) the following impact severity was calculated for the frontal plane impact with the embankment:

		Calculated Velocity Change - kph (mph)				
Vehicle	Variable	Total	Longitudinal	Latitudinal		
Case Vehicle (A)	EBS	26 (16)	-26 (-16)	0 (0)		

#### Exterior Damage

(Slides 10, 11, 12, 13, 14) Damage to case vehicle (A) was moderate. Direct-damage length from the frontal impact was 89 cm and began at the right-front bumper corner. Maximum crush was 24 cm and occurred at the right-front bumper corner. The front bumper, right headlight assembly, radiator, and both fenders were damaged. The right-front wheel was displaced 31-cm rearward, and this damage probably caused the airbag to deploy. The hood was damaged, and the hood latch released. Both of the hood hinges were damaged, the rear edge of the hood was elevated, but did not contact the windshield.

As a result of case vehicle (A) rolling over, the right upper A-pillar and left and right-upper B-pillars were damaged, and there was minor deformation of the right side of the windshield header with associated stress cracks in the windshield. The left quarter panel was crushed vertically and the left fiberglass outer door skin was missing from the vehicle. (Slides 15, 16, 17) The hatchback frame was torn from the vehicle and the rear window was shattered. The hatchback striker post mount separated from the body of the vehicle and was found attached to the latch.

# Interior Damage

(Slides 18, 19, 20, 21, 22, 23, 24) This vehicle was equipped with both steering-wheel and a passenger frontal-impact airbags, which deployed during the frontal impact. No damage was noted to the airbag skin or the module doors/flaps. (Slides 25, 26, 27, 28, 29) There was minor damage to the interior of the vehicle. The left-front armrest was dented from driver contact, the right-front floor pan was buckled, and both the side windows and the rear window were shattered.

The following intrusion was noted and measured:

Location	Component	Distance (cm)	Direction
Right front	Floor	10	Up

# Occupant Injuries and Kinematics

(Slides 30, 31) The 18-year-old male driver was reportedly wearing the available three-point belt and the airbag deployed. During the frontal impact, he moved forward and to the right relative to the vehicle and into the deploying airbag. (Slides 32, 33, 34, 35) He sustained a laceration over the right side of his forehead, possibly from contact with the roof/T-top. He sustained two 3-cm lacerations to the left elbow, and multiple superficial lacerations to the dorsal left hand and medial right humerus, probably from flying glass. He also sustained a lumbar strain due to impact forces.

(Slide 36) The attached table summarizes the injuries sustained by the driver.

Occupant: Driver Restraints: 3-point belt worn; airbag deployed

Age: 18 years Stature: 178 cm (5 ft 10 in)

Sex: Male Mass: 82 kg (180 lb)

			Injury Source	
Injury Description	A.I.S.	Definite	Probable	Possible
Laceration to the right side of forehead	1			Roof/T-top
Two 3-cm lacerations to the left elbow	1		Flying glass	
Multiple superficial lacerations to dorsal left hand	1		Flying glass	
Multiple superficial lacerations to right medial humerus	1		Flying glass	
Lumbar strain	1	Impact forces		
	:			
	i i			
Maximum A.I.S. Level	1			
Injury Severity Score	<u>2</u>			

VERSION 05	1996	ADMINISTRATIVE AD-1
TEAM CODE  ACCIDENT ID	30 03731	NO. OF CASE VEHICLES IN ACCIDENT  NUMBER OF SLIDES  15  15
VEHICLE NUMBER	-3 <del>7</del>	TEAM REPORT NUMBER
MODULE FORMAT	<u>A</u> D <u>Q</u> 1	$\frac{Um-3731-98}{18}$
FORM VERSION	<u>0</u> <u>5</u>	28 37
SPECIAL (00)		99

DATE OF FIELD INVESTIGATION: 198
INVESTIGATOR: LOCATION WHERE VEHICLE WAS EVALUATED:

CIRCLE PHOTO RECORDS MADE:



(01) Offset Frontal (98) Not Applicable

**NEGATIVES** 

**POLAROIDS** 

REPORT PREPARED BY:

Duplicate columns 1-8 Module G   Format C from the previous card. 9 10 1	1 .12	GENERAL INFORMATION	GI-1
TIME  DATE OF COLLISION / d  HOUR OF COLLISION 22	_	ENVIRONMENTAL CONDITIONS  CONSTRUCTION ZONE  (0) NO (1) YES (9) UNKNOWN  ROAD ALIGNMENT VERTICAL PLANE	31
LOCATION STATE: STATE FIPS CODE	26	(1) LEVEL (2) CREST OF HILL (3) SLOPE (2%) (4) BOTTOM OF HILL (9) UNKNOWN  ROAD ALIGNMENT HORIZONTAL PLANE	1
AREA (1) URBAN (2) RURAL (9) UNKNOWN	2 25	(1) STRAIGHT (2) CURVE (3) T - SHAPED (4) Y - SHAPED (7) OTHER:	3
ENVIRONMENTAL CONDITIONS  LIMITED-ACCESS HIGHWAY  (0) NO  (1) YES  (9) UNKNOWN	<u></u>	SURFACE COVERING  (10) DRY  (21) WATER - DAMP (22) WATER - WET (23) WATER - PUDDLED (29) WATER - AMOUNT UNKNOWN	1 0
ROAD, TOTAL TRAFFIC LANES (FOR CASE VEHICLE)  (1) 1-LANE (2) 2-LANES (3) 3-LANES (4) 4 OR MORE LANES (5) DIVIDED, 4 OR MORE LANES (6) PARKING LOT/DRIVEWAY (7) OTHER: (9) UNKNOWN	2	(31) SNOW - LOOSE (32) SNOW - PACKED (39) SNOW - CONDITION UNKNOWN  (41) ICE (51) SLUSH (61) SPILLED GRAVEL (71) OTHER: (99) UNKNOWN  VISIBILITY LIMITATION (FOR CASE VEHICLE)	
INTERSECTING RD, TOTAL LANES  CHOOSE FROM ABOVE LIST, OR  (8) NOT APPLICABLE .	<u>Z</u>	(0) NONE (1) CLOUDY/DARK (2) FOG (3) SMOKE (4) WINDSHIELD CONDITION (5) GLARE	Q
TYPE OF ROAD SURFACE  (1) ASPHALT (2) CONCRETE (3) GRAVEL (4) MORE THAN ONE (CIRCLE EACH) (7) OTHER: (9) UNKNOWN	23	(6) RAIN (7) OTHER: (8) ICE/SNOW (9) UNKNOWN  VISIBILITY OBSTRUCTION (FOR CASE VEHICLE)  (0) NONE	Φ
ROAD DEFECTS  (0) NO (1) YES (9) UNKNOWN	<u>Ø</u>	(1) BUILDING (2) SIGN (3) VEGETATION (E.G. BUSHES, SHRUBS) (4) TREE (5) HILL OR CURVE IN ROAD (6) VEHICLE IN TRANSPORT (7) OTHER: (8) PARKED VEHICLE (9) UNKNOWN	37

		GENERAL II	NFORMATION GI-2
ENVIRONMENTAL CONDITIONS  SPEED LIMIT  (0) 5-45 km/h 5-25 mph (1) 46-55 30 (2) 56-60 35 (3) 61-70 40 (4) 71-79 45 (5) 80-85 50 (6) 86-90 55 (7) 91-105 60 (8) OVER 105 65 (9) UNKNOWN	6 38	MECHANICAL MALFUNC WAS THERE MENTION OF A MECHANICAL MA IN CASE VEHICLE  (0) NO (1) YES (2) YES, DID NOT CONT TO ACCIDENT (9) UNKNOWN	ALFUNCTION Q
PRECIPITATION  (0) NONE (1) RAIN (2) SNOW (3) HAIL (4) FREEZING RAIN/SLEET (7) OTHER: (9) UNKNOWN  RATE OF PRECIPITATION  (1) LIGHT/MIST (2) MODERATE (3) HEAVY (8) NOT APPLICABLE (9) UNKNOWN  TEMPERATURE  (0) BELOW -15° C BELOW 5° F (1) -15 TO -6	Ø 39 8 40 9 41 .	THE FOLLOWING SECTION SHOOT IF A MECHANICAL MALFUR RECOGNIZED OR SUSPECTED.  CIRCLE ITEMS INVOLVED. SUFITEMS CIRCLED WITH COMMENTED STEMS SYSTEM STEERING SYSTEM SUSPENSION SYSTEM ELECTRICAL SYSTEM THROTTLE CONTROLS OTHER:	PPORT ANY VIS.  DRIVER CONTROLS POWER TRAIN FUEL SYSTEM VISIBILITY ITEMS TIRES UNKNOWN
CROSSWIND  (0) NONE (1) LIGHT (2) STRONG (3) GUSTY & STRONG (9) UNKNOWN  LIGHT CONDITIONS  (1) DAYLIGHT (2) DAWN (3) DUSK (4) DARK, LIGHTED (5) DARK, UNLIGHTED (6) DARK, UNKNOWN IF LIGHTED (9) UNKNOWN	9. 5.		

		GENERAL INFORMATION	GI-3
CRASH DETAILS  CASE VEHICLE AND OBJECT  (0) NO (1) YES (9) UNKNOWN  CASE VEHICLE ROLLOVER  (0) NO ROLLOVER (1) YES, FIRST EVENT (2) YES, SUBSEQUENT EVENT (3) YES, SEQUENCE UNKNOWN (9) UNKNOWN	1 2 45	HIGHEST POLICE INJURY SEVERITY CODE IN CRASH (NOT JUST CASE VEHICLE)  (0) O - NO INJURY (1) C - POSSIBLE INJURY (2) B - NON-INCAPACITATING INJURY (3) A - INCAPACITATING INJURY (4) K - FATAL (5) INJURED, SEVERITY UNKNOWN (6) DIED PRIOR TO ACCIDENT (7) NON-FATAL INJURY SEVERITY UNKNOWN (9) UNKNOWN	2 =
CASE VEHICLE RAN OFF ROADWAY (BEFORE FIRST IMPACT)  (0) NO (1) YES (9) UNKNOWN	47	DRIVER IMPAIRMENT  DRIVER ALCOHOL INVOLVEMENT (CASE VEHICLE)  (0) NONE (1) YES (9) UNKNOWN/NOT REPORTED/ NO DRIVER	<u>Ø</u>
MOVING CASE VEHICLE AND CONTACTED MOVING VEHICLE  (0) NO (1) YES (9) UNKNOWN	<u>Q</u>	DRIVER ALCOHOL BAC (CASE VEHICLE)  (80) NO TEST (90) CHEMICAL TESTS, NO RESULTS (95) AUTOPSY, NO RESULTS (99) UNKNOWN	. <u>8 0</u>
CASE VEHICLE AND CONTACTED STOPPED VEHICLE  (0) NO (1) YES (9) UNKNOWN	<u>Q</u>	WAS THERE MENTION OF DRIVER IMPAIRMENT FOR CASE VEHICLE?  (0) NO (1) YES (9) UNKNOWN	<u>Ø</u>
STOPPED CASE VEHICLE AND CONTACTED VEHICLE  (0) NO (1) YES (9) UNKNOWN	<u>چ</u>	LIST IMPAIRMENTS MENTIO	NED:
TOTAL NUMBER OF VEHICLES CONTACTED BY CASE VEHICLE IN CRASH  (8) 8 OR MORE (9) UNKNOWN	51	POST - CRASH DETAIL  MANNER CASE VEHICLE LEFT SCENE	
ANY FIRE IN THIS CRASH (NOT JUST CASE VEHICLE)  (0) NO (1) YES (9) UNKNOWN	<b>Q</b>	(1) DRIVEN (2) TOWED DUE TO DAMAGE (3) TOWED, NOT DUE TO DAMAGE (4) TOWED, REASON UNKNOWN (9) UNKNOWN	2 3

# ACCIDENT SCHEMATIC

ACCIDENT DESCRIPTION: Case vehicle (A) was traveling southbound. The CASE VEHICLE (A): 1998 Chevrolet C	amard	<u>ਨ</u>
driver reportedly fell asleep, and case vehicle (A) drifted off of the OTHER VEHICLE (B):		42
right shoulder as it approached a 3-leg intersection. (ase vehicle (A) THIRD VEHICLE (C): N/A		
Struck a culvert and impacted the embankment with its front end and the culvert with its right front u	sheel.	
Case vehicle (A) then vaulted and rolled over 4-quarter turns before coming towest on its wheels		
in a cornfield, south west of the intersection, and facing east		
	NORTH	
A4 Corn field		
Culvert		
Gouge in turf		
Paved		
Faveu		
	A	
		David
		<u>Paved</u>
Not posted 55 mph		

Duplicate columns 1-8 Module O V Format 0 1 from the previous card. 9 10 11 12	OTHER VEHICLE O	V-1
MAKE:	CARGO:	
MODEL:		
VIN	29	
MANUFAC/BODY CODE	VEHICLE TYPE	
MAKE/MODEL CODE	PASSENGER VEHICLE (02) LARGE (03) LIMOUSINE (17) PICKUP CAR (20) UNKNOWN PASSENGER VEHICLE BODY	4 55
MODEL YEAR NOT APPLICABLE 1 9	(24) SUB-MINI (25) MINI (26) SUB-COMPACT (27) COMPACT (28) INTERMEDIATE	
VEHICLE MASS (kg)	(29) FULL	
IF SEPARATE REPORT WAS MADE, GIVE VEHICLE NUMBER	MULTIPURPOSE PASSENGER VEHICLE (14) SMALL UTILITY (WHEELBASE LESS THAN 107', E.G. JEEP, BRONCO) (15) LARGE UTILITY (WHEELBASE MORE THAN 107', E.G. PANEL TRUCK, SUBURBAN)	
NUMBER OF OCCUPANTS (ENTER 9'S IF UNKNOWN)  49	(16) PICKUP TRUCK WITH CANOPY/SHELL COVER (17) PICKUP CAR WITH CANOPY/SHELL COVER (21) MOTOR HOME (22) PICKUP TRUCK WITH SLIDE-IN CAMPER (23) PICKUP CAR WITH SLIDE-IN CAMPER (31) CHASSIS-MOUNTED CAMPER	
TRAVELING SPEED (km/h)		
(000) PARKED OR STOPPED (995) JUST STARTING UP (996) BACKING UP (997) SPEED NOT EXCESSIVE (BUT UNKNOWN) (998) SPEED EXCESSIVE (BUT UNKNOWN) (999) UNKNOWN	TRUCK (11) VAN (12) PICKUP TRUCK (13) UNKNOWN LIGHT TRUCK (15) LARGE UTILITY (E.G. PANEL TRUCK, SUBURBAN) (16) PICKUP TRUCK WITH CANOPY/SHELL COVER (22) PICKUP TRUCK WITH SLIDE-IN CAMPER (30) UNKNOWN TRUCK TYPE (31) CHASSIS-MOUNTED CAMPER (33) DELIVERY VAN (WALK-IN)	
HIGHEST POLICE INJURY SEVERITY CODE FOR THIS VEHICLE  (0) O - NO INJURY	(34) STRAIGHT TRUCK (35) TRUCK-TRACTOR (BOBTAIL) (36) CHASSIS-CAB (37) UNKNOWN HEAVY TRUCK (38) TRACTOR & SEMI-TRAILER (SEMI) (39) TRUCK (OR SEMI) & FULL TRAILER(S)	
(1) C - POSSIBLE INJURY (2) B - NON-INCAPACITATING INJURY (3) A - INCAPACITATING INJURY (4) K - FATAL (5) INJURED, SEVERITY UNKNOWN (6) DIED PRIOR TO ACCIDENT	BUS (40) UNKNOWN BUS TYPE (41) SCHOOL BUS (42) INTERCITY BUS GETWEEN CORES	
(8) DIED FAICH TO ACCIDENT (7) NON-FATAL INJURY SEVERITY UNKNOWN (8) UNOCCUPIED VEHICLE (NOT APPLICABLE)	(42) INTERCITY BUS (BETWEEN CITIES) , (43) TRANSIT BUS (INTRACITY) (44) STREETCAR (ON TRACKS)	
(9) UNKNOWN	(68) TRAIN (CARS) (69) LOCOMOTIVE (ENGINE, SWITCHER)	
:	(99) UNKNOWN	
	WHEELBASE (cm) (999) UNKNOWN 56	57 58

plicate columns 1-8 m the previous card.	Aodule <u>O</u>	<u>V</u> 1	Format <u>0</u>	2 12	OTHER	VEHICLE	OV-2
			ORIGII	NAL SPECI	FICATIONS		
Wheelbase			cm		Front Overhang	22 - 24	cm
Curb Weight		<del>:</del>	kg		Rear Overhang	25 - 27	cm
Average Track Width	13	15	cm		Undeformed End Width (UEW)	28 30	cm .
Overall Length	<del></del>	18	cm		Engine Displacement	31 32	Ĺ
 Overall Width (OAW)	19	21	cm		Engine: # of Cylinders	33 34	

# VEHICLE DAMAGE

# NOT APPLICABLE


FRONTAL CRASH OVERLAP								
Round up for .5. 98 = 98% or more Enter % overlap or "99" for missing or N/A.	Direct Damage Length (DDL)	cm						
Front-End Overlap (Percent) = DDL UEW		% 38 39						
Vehicle Overlap (Percent) = DDL + 1/2 (OAW - UEV OAW	<u> </u>	40 41						

Duplicate columns 1-8 Module V D Format 0 1 from the previous card.	VEHICLE DESCRIPTION VI	D-1
MAKE: Chevrolet  MODEL: Camaro T-Top	CARGO:	
VIN 13		29
MANUFAC/BODY CODE $\frac{1}{30}$ $\frac{1327}{34}$	STOLEN VEHICLE	·
MAKE/MODEL CODE $0.12 \frac{1}{38}$	(0) NO (1) YES (8) NOT COLLECTED (9) UNKNOWN	<u>8</u>
MODEL YEAR 1 9 9 8	•	
VEHICLE MASS (kg) $0 0 0 5 6 6$ ODOMETER (km) (ENTER 9'S IF UNKNOWN) (ENTER 8'S IF ELECTRONIC)  NUMBER OF OCCUPANTS (ENTER 9'S IF UNKNOWN)  9999	BODY STRUCTURE  (1) BODY & FRAME (2) UNITIZED (3) INTEGRAL-STUB FRAME (4) BODY & PLATFORM FRAME (E.G. VW BUG) (5) PARTIALLY UNITIZED (7) OTHER: (9) UNKNOWN	<u>2</u>
TRAVELING SPEED (km/h)  (000) PARKED OR STOPPED (995) JUST STARTING UP (996) BACKING UP (997) SPEED NOT EXCESSIVE (BUT UNKNOWN) (998) SPEED EXCESSIVE (BUT UNKNOWN) (999) UNKNOWN	TRANSMISSION  (0) NONE (1) AUTOMATIC (2) MANUAL (9) UNKNOWN	1 62
VEHICLE TYPE  PASSENGER VEHICLE (11) 2-DOOR HARDTOP (NO UPPER B-PILLAR) (12) 2-DOOR SEDAN OR COUPE (ANY UPPER B-PILLAR) (13) 4-DOOR HARDTOP (14) 4-DOOR SEDAN (15) STATION WAGON (16) CONVERTIBLE (18) OTHER PASS. VEH.:	LOCATION OF TRANSMISSION SELECTOR LEVER  (1) FLOOR (2) CONSOLE (3) COLUMN (7) OTHER: (9) UNKNOWN	2 50
(19) PASSENGER VEHICLE, TYPE UNKNOWN  MULTIPURPOSE PASSENGER VEHICLE (21) SMALL UTILITY (E.G. JEEP, SCOUT, BRONCO) (22) LARGE UTILITY (E.G. PANEL TRUCK, SUBURBAN) (23) VAN, SIZE UNKNOWN (24) VAN, SMALL (MINI) (25) VAN, LARGE (29) MPV, TYPE UNKNOWN (30) MOTOR HOME	STEERING  (1) POWER (2) MANUAL (9) UNKNOWN	64
TRUCK (31) PICKUP TRUCK, UNKNOWN (32) PICKUP TRUCK, SMALL (DOWNSIZED) (33) PICKUP TRUCK, LARGE (99) UNKNOWN	BRAKES  (1) POWER  (2) MANUAL  (9) UNKNOWN	65

		VEHICLE DESCRIPTION VD-2
TYPE OF BRAKES  (1) DRUM, ALL WHEELS (2) DISC, FRONT WHEELS (3) DISC, ALL WHEELS (9) UNKNOWN	2 66	WHEELBASE <i>(cm)</i> (999) Unknown
BRAKE ANTI-LOCK DEVICE  (0) NONE INSTALLED (1) TWO-WHEEL (2) FOUR-WHEEL (7) EQUIPPED, UNKNOWN WHEELS (9) UNKNOWN  AIR CONDITIONING IN VEHICLE	2 57	PLASTIC ANTI-LACERATIVE INNER LAYER GLASS EQUIPPED  (0) NONE (1) WINDSHIELD (2) WINDSHIELD AND SIDE (7) OTHER (9) UNKNOWN
(0) NO (1) YES (8) NOT COLLECTED (9) UNKNOWN	8 66	
TYPE OF DRIVE  (1) REAR WHEEL (2) FRONT WHEEL (3) FOUR WHEEL (4) ALL WHEEL DRIVE (9) UNKNOWN	<u>l</u>	FIELD INVESTIGATOR INSTRUCTIONS:  1. INDICATE CRUSHED AREAS BY <u>OUT-</u> LINING NEW PERIMETER OF VEHICLE AND SHADING THE DAMAGED AREAS ON THE LARGE SKETCH ON PAGE VD-3.
OUAL REAR WHEELS  (0) NO (1) YES (9) UNKNOWN	70	USE AS MANY SKETCHES AS NECESSARY TO COMPLETELY DESCRIBE THE DAMAGE.  2. ENTER THE DIMENSIONS ON THE SKETCH(ES) MEASURED TO THE POINT OF MAXIMUM PENETRATION BY THE OBJECT(S) CONTACTED. USE THE EXAMPLES BELOW AS A GUIDE.
ORIGINAL TYPE OF RESTRAINT SYSTEM  (1) ACTIVE BELT (2) PASSIVE BELT (3) AIRBAG (4) KNEE BOLSTERS (7) OTHER: (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN	3,	3. ENTER THE THREE DIMENSIONS TO THE CENTER OF THE WHEELS (WHEELBASE, FRONT AND REAR OVERHANGS) ON BOTH SIDES OF THE CAR.  4. ADD OTHER DIMENSIONS AS NECESSARY TO COMPLETELY DESCRIBE THE DAMAGE.  EXAMPLES:
EQUIPPED WITH ROLL BAR  (0) NO (1) YES (9) UNKNOWN	Q	FRONT OR REAR
TYPE OF ROOF  (0) NONE (1) SOLID (2) T-TOP CLOSED (3) T-TOP OPEN (4) SUN ROOF CLOSED (5) SUN ROOF OPEN (6) CONVERTIBLE CLOSED (7) CONVERTIBLE OPEN (8) OTHER: (9) UNKNOWN	73	ROOF (REFERENCE TO TOP OF DOOR SALL OR WINDOW SILL)

Duplicate columns 1-8 from the previous card.	Module V D Format 0 2	VEHICLE DES	CRIPTION VD-3
	ORIGINAL S	PECIFICATIONS	/
Wheelbase	25'/ cm	Front Overhang	1 1 5 cm
Curb Weight	1566 kg	Rear Overhang	1 2 cm
Average Track Width	$1 \frac{1}{13} \frac{5}{15} \frac{4}{15}$ cm	Undeformed End Width (UEW)	146 cm
Overall Length	$\frac{49}{16} = \frac{1}{18}$ cm	Engine Displacement	3.8 .
Overall Width (OAW)	109	Engine: # of Cylinders	<u>p</u> 6

# **VEHICLE DAMAGE**



# FRONTAL CRASH OVERLAP

Round up for .5. 98 = 98% or more Enter % overlap or "99" for missing or N/A.

Direct Damage Length (DDL)

 $\underbrace{0}_{35} \underbrace{8}_{37} \operatorname{cn}$ 

Front-End Overlap (Percent) = DDL UEW

<u>b</u>] %

Vehicle Overlap (Percent) = DDL + 1/2 (OAW - UEW)
OAW

5 8 %

	A Format 0 2	DAMAGE DA-
PRIMARY	CASE VEHICLE PRIMARY CDC	CONTACTED VEHICLE ASSOCIATED CDC
EVENT NUMBER		998
IMPACT SPEED (km/h)	799	35 36 37
ESTIMATED BY	17	<u>\$</u>
CRUSH (cm)	$ \underbrace{\mathcal{Q}}_{18} \underbrace{\mathcal{Z}}_{19} \underbrace{\mathcal{Z}}_{20} $	$\frac{9}{39} \frac{9}{40} \frac{8}{41}$
CDC #1	12. FRWN. 3	$\frac{9}{42}  3  \mathcal{Q}  \mathcal{Q} $
CDC #2	12.FZEW.L	98.00000.0 49
SECONDARY	CASE VEHICLE SECONDARY CDC	CONTACTED VEHICLE ASSOCIATED CD
SECONDARY	CASE VEHICLE SECONDARY CDC	CONTACTED VEHICLE ASSOCIATED CD
EVENT NUMBER	<u>a</u>	
IMPACT SPEED (km/h)	$\frac{9}{14} = \frac{9}{15} = \frac{9}{16}$	$\frac{9}{35} \frac{9}{36} \frac{9}{37}$
ESTIMATED BY	17	<u>8</u>
CRUSH (cm)	<u>Ø</u> <u>Ø</u> <u>3</u>	$\frac{998}{3940}$
CDC #1	<u>00 LDAO 2</u>	980000
CDC #2	$\frac{9}{3} \cdot 20000 \cdot 20$	98.0000.0
Codes		
EVENT NUMBER	IMPACT SPEED ESTIMATOR	CRUSH
(8) NOT APPLICAE (9) UNKNOWN	BLE (1) INVESTIGATOR (2) DRIVER (3) POLICE	(998) NOT APPLICABLE (NO VEHICLE/DAMAGE) (999) UNKNOWN
IMPACT SPEED	(4) *CRASH* PROGRAM (5) OTHER COMPUTER PROGRAM	CDC
(998) NOT APPLIC (999) UNKNOWN	ABLE SPECIFY:  (7) OTHER:  (8) NOT APPLICABLE  (NO VEHICLE/NO IMPACT)	(9800000) NOT APPLICABLE (9900000) UNKNOWN

Duplicate columns 1-8 Market from the previous card.	odule D A Format 0 1 12	_	DAMAGE DA-2
	MAXIMUM SHEE	ET METAL CRUSH	
	<i>(cm)</i> (999	9) UNKNOWN	
FRONT	<u>0</u> 24	RIGHT SIDE	$\frac{\emptyset}{16}$ $\frac{3}{18}$ .
REAR	<u>Ø</u> <u>Ø</u> <u>Ø</u>	LEFT SIDE	$ \underline{Q}_{z} \underline{Q} \underline{Q}_{z} $
ROOF	Ø 1 27	OTHER	$ \underbrace{\emptyset}_{\mathbf{z}} $
•			
		CAL SEQUENCE	
	OF DAMAGE/INJURY PRO		S
	FOR CASE	EVEHICLE	
IS UNKNOW ORDER IS C		DO YOU KNOW THE TO BE IN CHRONO (0) NO (1) YES	EUGICAL UNDER!
EVENT NUMBER	IMPACT LOCATION	IMPACT CONFIGURATION	OBJECT/VEHICLE CONTACTED
	(1) ON ROADWAY (2) SHOULDER/MEDIAN/GORE (3) ON ROADSIDE (4) OUTSIDE ROADSIDE RIGHT-OF-WAY (5) OTHER (6) OFF ROADWAY, LOC. UNK. (9) UNKNOWN	FOR CODES, SEE TABLE ON PAGE DA-3.	FOR CODES, SEE TABLE ON PAGE DA-4.
# 1	2	17	<u>82</u>
#2	32 4 37	6 2 3	8 4
#3	42	. — —	46
**	47	<del></del>	<del>- 51</del>
#4	1		
#4	52	<del></del>	<del>- 56</del>
	52 		——————————————————————————————————————

DA-3 DAMAGE

#### CODES FOR IMPACT CONFIGURATION

#### FRONT OF CASE VEHICLE

- (11) AND FRONT OF CONTACTED VEHICLE
- (13) AND SIDE OF CONTACTED VEHICLE
- (14) AND REAR OF CONTACTED VEHICLE
- (16) ENDSWIPED BY CONTACTED VEHICLE
- (17) AND OBJECT
- (19) AND UNKNOWN OTHER VEHICLE CONFIGURATION

# LEFT SIDE OF CASE VEHICLE

- (21) AND <u>FRONT</u> OF CONTACTED VEHICLE (TYPE T) (22) AND <u>FRONT</u> OF CONTACTED VEHICLE (TYPE L)
- (23) AND SIDE OF CONTACTED VEHICLE (NOT SIDESWIPE)
- (24) AND REAR OF CONTACTED VEHICLE (TYPE T)
  (25) AND REAR OF CONTACTED VEHICLE (TYPE L)
- (26) SIDESWIPED BY CONTACTED VEHICLE
- (27) AND OBJECT
- (29) AND UNKNOWN OTHER VEHICLE CONFIGURATION

#### **REAR OF CASE VEHICLE**

- (31) AND FRONT OF CONTACTED VEHICLE
- (33) AND SIDE OF CONTACTED VEHICLE
- (34) AND REAR OF CONTACTED VEHICLE
- (36) ENDSWIPED BY CONTACTED VEHICLE
- (37) AND OBJECT
- (39) AND UNKNOWN OTHER VEHICLE CONFIGURATION

#### RIGHT SIDE OF CASE VEHICLE

- (41) AND FRONT OF CONTACTED VEHICLE (TYPE T)
- (42) AND FRONT OF CONTACTED VEHICLE (TYPE L)
- (43) AND SIDE OF CONTACTED VEHICLE (NOT SIDESWIPE)
- (44) AND REAR OF CONTACTED VEHICLE (TYPE T) (45) AND REAR OF CONTACTED VEHICLE (TYPE L)
- (46) SIDESWIPED BY CONTACTED VEHICLE
- (47) AND OBJECT
- (49) AND UNKNOWN OTHER VEHICLE CONFIGURATION

#### OTHER

- (57) VEHICLE TO OBJECT
- (58) VEHICLE TO VEHICLE
- (59) VEHICLE TO VEHICLE, CONFIGURATION UNKNOWN

#### ROLLOVER

- (61) LESS THAN 360°
- (62) 360° OR MORE
- (69) DETAILS UNKNOWN

#### UNKNOWN

(99) IMPACT TYPE UNKNOWN

#### DAMAGE DA-4

#### CODES FOR VEHICLE/OBJECT CONTACTED

#### **VEHICLE/OBJECT GROUPS** BUS NO OBJECT (40) UNKNOWN BUS TYPE (00) (01) - (39) PASSENGER VEHICLE & TRUCK (41) SCHOOL BUS (40) - (69) OTHER VEHICLE (42) INTERCITY BUS (BETWEEN CITIES) (70) - (76) PEDESTRIAN & ON-ROADWAY OBJECT (43) TRANSIT BUS (INTRACITY) (77) - (97) OFF-ROADWAY OBJECT (44) STREETCAR (ON TRACKS) OTHER (DESCRIBE) (99) **UNKNOWN MOTORCYCLE** (50) UNKNOWN MOTORCYCLE TYPE (51) 1 - 75 ∞ (52) 76 - 125 ∞ PASSENGER VEHICLE (02) LARGE (03) LIMOUSINE (53) 126 - 250 cc (17) PICKUP (54) 251 - 500 cc (20) UNKNOWN PASSENGER VEHICLE BODY (55) 501 - 750 € (24) SUB-MINI (56) 751 cc + (57) 3-WHEELS (OR WITH SIDECAR) (25) MINI (26) SUB-COMPACT (27) COMPACT SPECIAL PURPOSE VEHICLE (60) UNKNOWN/OTHER SPECIAL VEHICLE (DESCRIBE) (28) INTERMEDIATE (61) SNOWMOBILE (29) FULL (62) ATV (ALL TERRAIN VEHICLE) (63) AMPHIBIOUS VEHICLE (64) FARM VEHICLE SIZE **WHEELBASE** (65) CONSTRUCTION VEHICLE (66) TRAILER, PRIVATE (CAMPER) SUB-MINI < 2286 mm ( < 90°) (67) TRAILER, COMMERCIAL (CARGO) MINI 2286 - 2412 mm (90° - 94.9°) SUB-COMPACT 2413 - 2539 mm (95° - 99.9°) (68) TRAIN (CARS) 2540 - 2666 mm (100° - 104.9°) (69) LOCOMOTIVE (ENGINE, SWITCHER) COMPACT INTERMEDIATE 2667 - 2793 mm (105" - 109.9") 2794 - 2920 mm (110° - 114.9°) FULL **OBJECT** LARGE 2921 - 3174 mm (115" - 124.9") (70) PEDESTRIAN LIMOUSINE > 3175 mm ( > 125°) (71) BICYCLIST, OTHER PEDALCYCLIST (72) PEDESTRIAN CONVEYANCE (E.G. PERSON RIDING MULTIPURPOSE PASSENGER VEHICLE ANIMAL CART) (11) SMALL VAN (MINI) (73) LARGE ANIMAL (12) PICKUP (74) FALLEN OBJECT (E.G. OBJECT DISLODGED FROM (14) SMALL UTILITY (WHEELBASE LESS THAN 107". OTHER VEHICLE, FALLEN TREE, ROCKS) (75) ROCKS E.G. JEEP, BRONCO) (76) CONSTRUCTION EQUIPMENT (EXCLUDING (65)) (15) LARGE UTILITY IWHEELBASE MORE THAN 107". (77) SIGN POST, UTILITY POLE, TREE E.G. PANEL TRUCK, SUBURBAN) (16) PICKUP TRUCK WITH CANOPY/SHELL COVER (78) DITCH (17) PICKUP CAR WITH CANOPY/SHELL COVER (79) EMBANKMENT, SNOWBANK, RR TRACKS RR X (21) MOTOR HOME (80) GROUND (ROLLOVER ONLY) (22) PICKUP TRUCK WITH SLIDE-IN CAMPER (81) CURB (DAMAGE PRODUCING IMPACTS ONLY) (23) PICKUP CAR WITH SLIDE-IN CAMPER (82) CULVERT (31) CHASSIS-MOUNTED CAMPER (83) FENCE (84) HYDRANT, SHORT POST, STUMP (85) SMALL POST/TREE, RURAL MAIL BOX, MILE TRUCK MARKER, DELINEATOR (11) SMALL VAN (E.G. ECONOLINE) (86) BUILDING (12) PICKUP TRUCK (87) PIER, PILLAR, BRIDGE SUPPORT (13) UNKNOWN LIGHT TRUCK (88) ABUTMENT, RETAINING WALL (15) LARGE UTILITY (E.G. PANEL TRUCK, SUBURBAN) (89) BRIDGE RAIL (16) PICKUP TRUCK WITH CANOPY/SHELL COVER (90) GUARD RAIL, LEADING SECTION (91) GUARD RAIL, MIDDLE OR UNKNOWN (92) GUARD RAIL, TRAILING SECTION (93) GUARD POST (TIMBER, METAL, CONCRETE) (22) PICKUP TRUCK WITH SLIDE-IN CAMPER (30) UNKNOWN TRUCK TYPE (31) CHASSIS-MOUNTED CAMPER (33) DELIVERY VAN (WALK-IN) (34) STRAIGHT TRUCK (94) CABLE, FENCE BARRIER (95) CONCRETE BARRIER (MEDIAN) (35) TRUCK-TRACTOR (BOBTAIL) (96) IMPACT ATTENUATOR (36) CHASSIS-CAB

(97) BREAKAWAY FEATURES

(37) UNKNOWN HEAVY TRUCK (38) TRACTOR & SEMI-TRAILER (SEMI) (39) TRUCK (OR SEMI) & FULL TRAILER(S)

	CASE VEHICLE P		r ΔV	CONDARY IMPACT	
	CASE VEHICLE P	CONTACTED	CASE VEHICLE SECONDARY IMPAC		
	VEHICLE	VEHICLE	VEHICLE	VEHICLE	
EVENT NUMBER	13		47		
ΔV (km/h) TOTAL	$\frac{9}{14} \frac{9}{15} \frac{9}{16}$	$\frac{g}{3}\frac{g}{3}\frac{g}{3}$	48 49 50	66 67 68	
LONGITUDINAL*	$\frac{9}{17} \frac{9}{9} \frac{9}{20}$	$\frac{8}{8} \frac{8}{8} \frac{3}{8}$	51 54	69 7	
LATERAL*	9999	8888			
*NOTE: THESE $\Delta$ V COMPONENTS MUST INCLUDE SIGN.	21 24	39 42	55 <b>58</b>	73 7	
EXAMPLES: 10 km/h = ± <u>0</u> 1 <u>0</u> -7 km/h = <u>:</u> <u>0</u> <u>0</u> <u>7</u>		:			
ENERGY DISSIPATED BY CRUSH (kj)	9999	8888	59 62	<del>77</del> — — <del>6</del>	
RECONSTRUCTION					
(01) RECONSTRUCTED, UNKNOWN CONFIDENCE LEVEL	$ \underline{Q}_{\frac{2}{30}} $		63 64		
(21) RECONSTRUCTED, LOW CONFIDENCE LEVEL	29 30		w w		
(22) RECONSTRUCTED, MODERATE CONFIDENCE LEVEL (23) RECONSTRUCTED, HIGH CONFIDENCE LEVEL					
NOT RECONSTRUCTED BECAUSE					
(02) INSUFFICIENT DATA (03) EXCESSIVE UNDERRIDE/ OVERRIDE (04) ROLLOVER (05) VAULTING (06) OTHER TRAVEL IN MORE					
THAN ONE PLANE (07) NON-HORIZONTAL FORCE (08) SIDESWIPE-TYPE DAMAGE (09) YIELDING OBJECT		,			
(10) OTHER:				**	
MODE					
(1) CDC ONLY (2) CDC & DETAILED DAMAGE (3) TRAJECTORY & CDC (4) TRAJECTORY & CDC & DETAILED DAMAGE (5) NOT RECONSTRUCTED	31		65		
COMPUTER PROGRAM					

Duplicate columns 1-8 from the previous card.  Module C R 9 10	Format 0 2		H RECONSTRUCT	TION CR-2		
	CASE VEHICLE P	PRIMARY IMPACT CASE VEHICLE SECONDARY IMPACT				
	CASE VEHICLE	CONTACTED VEHICLE	CASE VEHICLE	CONTACTED VEHICLE		
EVENT NUMBER	13		47			
EBS (km/h) TOTAL	$ Q_{\frac{14}{15}} \frac{2}{15} \frac{6}{16} $	$\frac{8}{32} \frac{8}{33} \frac{8}{34}$	48 49 50	66 67 68		
LONGITUDINAL*	$\frac{-}{17}$ $\emptyset$ $\frac{6}{20}$	32 8 8 8 8	51 - 54	69		
LATERAL*	<u>+000</u>	8888	55 58	73		
NOTE: THESE EBS COMPONENTS MUST INCLUDE SIGN.	21 24	33				
EXAMPLES: 10 km/h = ± <u>0</u> 1 <u>0</u> -7 km/h = ± <u>0</u> <u>0</u> <u>7</u>						
ENERGY DISSIPATED BY CRUSH (kg)	<u>Ø</u> <u>Ø</u> <u>4</u> <u>2</u>	<u> 3888</u>	59 62	<del></del>		
RECONSTRUCTION	41,880					
(01) RECONSTRUCTED, UNKNOWN CONFIDENCE LEVEL	$\frac{21}{29}$		<u> </u>			
(21) RECONSTRUCTED, LOW CONFIDENCE LEVEL (22) RECONSTRUCTED, MODERATE CONFIDENCE LEVEL (23) RECONSTRUCTED, HIGH CONFIDENCE LEVEL	29 30					
NOT RECONSTRUCTED BECAUSE		ţ		<u>-</u>		
(02) INSUFFICIENT DATA (03) EXCESSIVE UNDERRIDE/ OVERRIDE (04) ROLLOVER (05) VAULTING (06) OTHER TRAVEL IN MORE THAN ONE PLANE (07) NON-HORIZONTAL FORCE (08) SIDESWIPE-TYPE DAMAGE (09) YIELDING OBJECT (10) OTHER: (11) AT'LEAST ONE VEHICLE BEYOND SCOPE (12) OTHER VEHICLE NOT INSPECTED						
MODE						
(1) CDC ONLY (2) CDC & DETAILED DAMAGE (3) TRAJECTORY & CDC (4) TRAJECTORY & CDC & DETAILED DAMAGE (5) NOT RECONSTRUCTED	$\frac{2}{31}$		65			
COMPUTER PROGRAM SPECIFY: WINSMASH						

	te columns 1-8 previous card.	Module <u>C</u>	R_Form	at <u>0 3</u>	-	CRASH	RECON	STRUC	TION	CR-3
NOTES	2. MEAS		FROM DRIVER	R TO PASSENG	ASUREMENTS IN <u>C</u> SER SIDE IN FRONT			C	ASE VE	HICLE
					NRD OF OR TO THE	20.505			LOCAT	OR
•		HE CENTER OF				HIGHT OF IF	1E CG.			
Locate					udinal center line,	or an undam	aged axie	for side in	npacts.	
Specific	Impact No.		Location of	f Direct Dar	mage		Locat	ion of Fi	eld L	· · · · · · · · · · · · · · · · · · ·
		Begins	1 from	t bume	or Corner	B.C	6 B.C			•
		3								
Specific Impact	LANE: (1) Bumper (2) Above Bu (3) Sill (4) Above Si (5) Other (9) Unknown NOTE: Each Plane of Impact	line in the tab	CRUSI	C6 C5 C4 C2 C1 H PROFILE separate rec		Duplicate co	i	2 for each	Complete	-
Number	C-Measur.	Length (DDL)	Crush	L	C <sub>1</sub> C <sub>2</sub>		C <sub>4</sub>	C <sub>5</sub>	C <sub>6</sub>	±D
<u> </u>	Bumper	89	C4	105	38 33	5 53	55	39	NO	+22
	Freespace		!		-30 -15	5 - 9	- 4	-15	-30	
		<u> </u>		-		<u> </u>				
					:	İ				
	ļ				1.					
1	1	089	024	103	008 01	8024	024	019	eio	+025
13	14	15 16 17	18 19 20	2: 22 23	24 25 26 27 28	29   30 31 32	33 34 35	36 37 38	39 40 41	42 43 44 45
	1					- <del> </del>				
	<u>†</u>				: : ; ;					
_										
2										

	columns 1-8 revious card.	Module <u>C</u>	R Format	0 4		CR	ASH R	ECONS	TRUCTI	ON	CR-4
NOTES:	2. MEASUF IMPACTS 3. D IS POS	CRASH RECON.  RE C <sub>1</sub> TO C <sub>6</sub> FR.  REAR TO FROM  STIVE IF MEAS  E CENTER OF 1  mage with res	OM DRIVER TO ONT IN SIDE IM URED TO A PO THE WHEELBAS	O PASSENGE IPACTS. DINT FORWAR SE AS THE CO	R SIDE IN F D OF OR TO S.	RONT OR I	REAR HT OF THE		LC	R VEHI	_
Specific Impact No. Location of Direct Damage Location of Field L											
			<del></del>						·		
		····	<del></del>								
PLANE:  (1) Bumper (2) Above Bumper (3) Sill (4) Above Sill (5) Other (9) Unknown  CRUSH PROFILE IN CENTIMETERS  NOTE: Each line in the table below is a separate record (card).  DL UDL  CRUSH PROFILE IN CENTIMETERS  Duplicate columns 1 - 12 for each completed line.							d line.				
Specific Impact	Plane of Impact	Direct	Damage Max	Field	C <sub>1</sub>	C <sub>2</sub>	C3	C <sub>4</sub>	C <sub>5</sub>	C <sub>6</sub>	±D
Number	C-Measur.	Length (DDL)	Crush	L	•	<b>6-</b>					
			.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,								
1											
13	14	15 16 17	18 19 20	21 22 23	24 25 26	27 28 29	30 31 32	33 34 35	36 37 38	39 40 41	42 43 44 45
				1							
	1			† †							
2											

Duplicate columns 1-8 from the previous card.  Module W T 10	Format <u>0</u>	1 12	WHEELS AND TIRES WT-1
WHEELSDAMAGED  (0) NO (1) YES (9) UNKNOWN	LF RF RR LR		SIZE (NOT DOT CODE. IF UNKNOWN, USE 9'S)  LF P 3 5 5 5 R 1 6  RF P 3 3 5 5 5 R 1 6  RR P 3 3 5 5 5 R 1 6
TIRE TREAD TYPE  (1) REGULAR (2) SNOW (3) SLICKS (4) ALL WEATHER (MS) (7) OTHER: (9) UNKNOWN	LĘ RF RR LR	4 4 4 4 4 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2	LR P23555R16_
CARCASS CONSTRUCTION  (1) BIAS (2) BELTED BIAS (3) RADIAL (4) ELLIPTICAL (5) HI PRESSURE SPARE (6) SPACE SAVER SPARE (7) OTHER: (9) UNKNOWN	LF RF RR LR	3 3 3 3	
IF VEHICLE IS EQUIPPED WITH DUAL WHEELS, COMPLETE FOR OUTER WHEELS AND MAKE NOTES ON INNER WHEELS.  NOTES:	s		

Duplicate columns 1-8 Module F T For from the previous card.	rmat <u>0 1</u>	FUEL AND FUEL TANKS	FT-1
TYPE OF PROPULSIVE FUEL  (1) GASOLINE (2) DIESEL OIL (3) LPG (4) ELECTRIC (7) OTHER: (9) UNKNOWN	13	AUXILIARY TANK TYPE  (1) OEM TANK (2) AFTER MARKET TANK (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN	21
MAIN TANK LOCATION	122	AUXILIARY TANK LOCATION	888
MAIN FILLER CAP LOCATION	113	AUXILIARY FILLER CAP LOCATION	888
MAIN TANK MATERIAL	1 20	AUXILIARY TANK MATERIAL	8 28

# TANK AND FILLER CAP LOCATION CODES

#### FIRST DIGIT (LONGITUDINAL)

- (1) BEHIND KICK-UP
- (2) IN KICK-UP
- (3) BETWEEN KICK-UP & COWL
- (4) FORWARD OF COWL
- (8) NOT APPLICABLE (NOT EQUIPPED)
- (9) UNKNOWN

#### SECOND DIGIT (LATERAL)

- (1) LEFT OF FRAME
- (2) WITHIN FRAME OR CENTERED
- (3) RIGHT OF FRAME
- (4) DUAL, RIGHT & LEFT TANKS
  (8) NOT APPLICABLE (NOT EQUIPPED)
- (9) UNKNOWN

# THIRD DIGIT (VERTICAL)

- (1) BELOW FRAME
- (2) WITHIN FRAME OR CENTERED
- (3) ABOVE FRAME
- (8) NOT APPLICABLE (NOT EQUIPPED)
- (9) UNKNOWN

# TANK MATERIAL CODES

- (1) STEEL
- (2) ALUMINUM
- (3) PLASTIC
- (7) OTHER
- (8) NOT APPLICABLE (NOT EQUIPPED)
- (9) UNKNOWN

Duplicate columns 1-8 from the previous card.

Module <u>F</u> <u>I</u> Format <u>0</u> <u>1</u> 12

FUEL LEAKAGE

FL-1

# DID FUEL LEAKAGE RESULT FROM A CRASH EVENT

(0) NO KNOWN LEAKAGE SKIP PAGE.

13

(1) YES COMPLETE PAGE.

	1	II	111	IV	V	
LEAK NUMBER	LEAKING COMPONENT	COMPONENT SOURCE	TYPE OF DAMAGE	SEVERITY OF DAMAGE	LOCATION OF LEAK	EVENT NUMBER
#1	14 15		_	_		21
#2	22 23	<del>-</del>	_	_		29
#3	30 31			_		37
#4	38 39	—		_	. ———	45
#5	46 47	· <u></u>		_		53

#### LEAKING COMPONENT

#### TANK AREA

- (11) MAIN FUEL TANK (INCLUDING VAPOR RECOVERY DOME)
- (12) AUXILIARY FUEL TANK
- (13) MAIN TANK FILLER TUBE
- (14) MAIN TANK CAP (GAS CAP)
- (15) AUXILIARY TANK FILLER TUBE
- (16) AUXILIARY TANK CAP (GAS CAP)
- (19) TANK AREA, DETAILS UNKNOWN

#### **DELIVERY SYSTEM**

- (21) FUEL FEED LINE (MAIN TANK TO FUEL PUMP)
- (22) FUEL FEED LINE (AUXILIARY TANK TO FUEL PUMP)
- (23) FUEL RETURN LINE (FUEL PUMP TO TANK)
- (24) INLINE FUEL FILTER
- (25) FUEL LINE (PUMP TO CARBURETOR OR INJECTOR PUMP)
- (26) CARBURETOR TO INJECTOR PUMP
- (27) FUEL PUMP
- (29) DELIVERY SYSTEM, DETAILS UNKNOWN

#### EVAPORATIVE EMISSION CONTROL SYSTEM

- (31) ATMOSPHERIC VENT PIPE (NON-EEC EQUIPPED)
- (32) EEC PIPE (VAPOR CANISTER TO CARBURETOR)

#### EEC SYSTEM (CONTINUED)

- (33) VAPOR RECOVERY HOSES (CANISTER TO CARBURETOR)
- (34) LIQUID-VAPOR SEPARATOR (UNLESS PART OF TANK)
- (35) CANISTER
- (39) EEC SYSTEM, DETAILS UNKNOWN
- (49) ENGINE COMPARTMENT, COMPONENT UNKNOWN
- (99) COMPONENT UNKNOWN

#### II COMPONENT SOURCE

- (1) OEM
- (2) AFTER MARKET
- (9) UNKNOWN

# III TYPE OF DAMAGE

- (1) DENTED/CRUSHED
- (2) PUNCTURED
- (3) RUPTURED
- (4) SEVERED/GROSS TEARS
- (5) DISCONNECTED/DEFEATED
- (9) UNKNOWN

# IV SEVERITY OF DAMAGE

- (1) MINOR
- (2) MODERATE
- (3) SEVERE
- (4) DISCONNECTED/DEFEATED
- (9) UNKNOWN

# V LOCATION OF LEAK

# FIRST DIGIT (LONGITUDINAL LOCATION)

- (1) F, FORWARD OF COWL
- (2) P. BETWEEN COWL & REAR BULKHEAD
- (3) B, BEHIND REAR BULKHEAD
- (4) Y, F, & P
- (5) Z, P, & B
- (6) D. DISTRIBUTED (F, P & B)
- (9) UNKNOWN

# SECOND DIGIT (LATERAL LOCATION)

- (1) L, LEFT
- (2) C, CENTER
- (3) R, RIGHT
- (4) Y, LEFT CENTER (L & C)
- (5) Z, RIGHT CENTER (R & C)
- (6) D. DISTRIBUTED (F, P & B)
- (9) UNKNOWN

Duplicate columns 1-8 Module F R Format 0 11 11	1 12	FIRE	FR-1				
WAS THERE FIRE IN OR ON CASE VEHICLE?  (0) NO <u>SKIP PAGE</u> .  (1) YES <u>COMPLETE PAGE</u> .							
DID FIRE START IN CASE VEHICLE?  (0) NO (1) YES (9) UNKNOWN	14	SEVERITY OF FIRE DAMAGE  (1) MINOR (2) MODERATE (3) SEVERE (9) UNKNOWN	16				
FLAME PROPOGATION RATE  (1) RAPID/EXPLOSIVE (2) SLOW/MODERATE (9) UNKNOWN	15	DID AN INJURY TO CASE VEHICLE OCCUPANT RESULT FROM FIRE IN OR ON CASE VEHICLE?  (0) NO (1) YES (9) UNKNOWN	17				

PROVIDE NOTES IF FIRE OCCURRED.

•

Duplicate columns 1-8 from the previous card.	Module <u>E</u>	D Format 0	EXTERIOR DAMAGE	ED-1
HOOD PERFORMAN	NCE		STEERING COL FLEXIBLE COUPLING	
FOR THE FOLLOWING, USE CODES:			FLEXIBLE COUPLING TYPE	
(0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN			(0) NONE (1) FLEXIBLE MATERIAL (2) POT (3) SINGLE U-JOINT (4) DOUBLE U-JOINT (5) FLEXIBLE CABLE (6) COMBINATION OF ABOVE (CIRCLE EACH)	9 26
HOOD LATCH(ES)-		-RELEASED	(7) OTHER: (8) EQUIPPED, TYPE UNKNOWN (9) UNKNOWN, IF EQUIPPED	
		-DAMAGED	COUPLING DAMAGED	9
		-JAMMED	COUPLINGDAMAGED  (USE CODES FROM HOOD PERFORMANCE) -SEPARATE (COMPLETE	27 D <u>9</u>
HOOD HINGES-	-LEFT,	DAMAGED		
	-LEFT,	SEPARATED (COMPLETE)		
	-RIGHT,	DAMAGED	ENG COMPART TELESCOPING UNIT	
HOOD REMAINED ON	-RIGHT, VEHICLE	SEPARATED (COMPLETE)	TYPE OF UNIT  (00) NONE INSTALLED  (01) - (07) SEE UNITS ON PAGE ED-2  (88) NOT COLLECTED  (97) OTHER:  (98) EQUIPPED, TYPE UNKNOWN  (99) UNKNOWN IF EQUIPPED	8 8 29 30
REAR EDGE OF HOOD	<b>.</b>	-ELEVATED	ORIGINAL LENGTH (mm)	
-co	NTACTED	WINDSHIELD	F (OR H):  TELESCOPED LENGTH (mm)	-
-PE1	NETRATED	WINDSHIELD	TELESCOPED LENGTH (mm)	
HOOD LATCH LOCATIO	ON			
(1) FRONT OF VEH (2) COWL AREA (3) SIDE (8) NOT APPLICAB (9) UNKNOWN			DIFFERENCE (mm)  F (OR H) - G  (IF LESS THAN 15mm, ENTER *000*.)	
ENGINE OR TRANSM SEPARATION (COMPL (0) NO (1) YES (9) UNKNOWN		Моинт	(888) NOT COLLECTED (991) NOT MEASURED/NO COMPRESSION (992) COMPRESSED, AMOUNT UNKNOWN (993) DEVICE EXTENDED (997) UNABLE TO BE MEASURED (998) NOT APPLICABLE (NOT EQUIPPED) (999) UNKNOWN	8 8 -


		EXTERIOR DAMAGE	ED-2
LEFT-SIDE BODY MOUNT DID BODY MOUNT SEPARATE?  (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	<u>8</u>	LEFT DOORS HOW DID DOORS OPEN DURING COLLISION?	
LEFT PILLARS  PILLARS SEPARATED COMPLETELY -  USE CODES:  (0) NO (1) YES (4) NO SEPARATION, BUT DAMAGED (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN  -A-PILLAR, UPPER	Ø 35  Ø 36		RONT 43
-B-PILLAR, UPPER LOWER	1 37 1 38	DOORS JAMMED CLOSED-  USE CODES:  (0) NO (1) YES (8) NOT APPLICABLE (NO DOOR)	
-C-PILLAR, UPPER LOWER	\$ \$ \\ \frac{1}{40} \]	(9) UNKNOWN -FI	RONT $\frac{0}{\frac{45}{2}}$
-D-PILLAR, UPPER . LOWER	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		

		EXTERIOR DAMAGE	ED-3
REAR DOOR  REAR DOOR TYPE  (0) NO DOOR (INCLUDES PICKUPS) (1) HATCHBACK (2) ONE-WAY TAILGATE (3) TWO-WAY TAILGATE (4) CLAMSHELL/DISAPPEARING TAILGATE (5) SINGLE DOOR (6) DOUBLE DOOR (9) UNKNOWN  Hatchback  One-way	47	OTHER REAR DAMAGE  WAS PARTITION TO LUGGAGE AREA DAMAGED DURING COLLISION?  (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN  SPARE TIRE  (0) NO SPARE TIRE (1) NOT ATTACHED BEFORE COLLISION (2) ATTACHED, NOT SEPARATED IN COLLISION (3) ATTACHED, SEPARATED DUE TO COLLISION (6) NOT COLLECTED (9) UNKNOWN	<u>8</u>
Two-way  Clamshell  Single door  Double door  HOW DID DOOR OPEN DURING COLLISION?		TRAILER HITCH TYPE  (0) NO HITCH  BALL-AND-SOCKET TYPES  (1) TEMPORARY FRAMEWORK (E.G. RENTAL CLAMP-ON)  (2) BUMPER-MOUNT ONLY (E.G. LIGHT TRUCK)  (3) BUMPER-AND-FRAME (BUT NON-EOUALIZING)  (4) LOAD EQUALIZING  OTHER TYPES  (5) RING-AND-PINTLE  (6) FIFTH-WHEEL (INCL P/U)  (7) OTHER (E.G. CLEVIS-AND-PIN)	<b>₽</b>
(0) DOOR DID NOT OPEN (atch  OPENED BECAUSE OF Separation  (1) HINGE AREA SEPARATION  (2) DOOR-LATCH SEPARATION  (3) LATCH-STRIKER SEPARATION  (4) STRIKER-PILLAR SEPARATION  (5) BODY DISTORTION  (6) COMBINATION OF ABOVE  (CIRCLE EACH)  (7) OPENED, REASON UNKNOWN  (8) NOT APPLICABLE (NO DOOR)  (9) UNKNOWN  DOOR JAMMED CLOSED  (0) NO  (1) YES  (8) NOT APPLICABLE (NO DOOR)	7 49 49	(8) EQUIPPED, TYPE UNKNOWN (9) UNKNOWN IF EQUIPPED  TRAILER TYPE (AT TIME OF COLLISION)  (0) NO TRAILER (1) TRAVEL-TRAILER/CAMPER (2) MOBILE HOME (3) BOAT/SNOWMOBILE/ATV TRAILER (4) UTILITY TRAILER (5) TOWED CAR (7) OTHER: (8) TRAILER, TYPE UNKNOWN (9) UNKNOWN	<u>s</u>

	EXTERIOR DAMAGE ED-4
<b>8</b> 3	RIGHT DOORS HOW DID DOORS OPEN DURING COLLISION?  USE CODES:
	(00) DOOR DID NOT OPEN  OPENED BECAUSE OF  (01) HINGE AREA SEPARATION (02) DOOR-LATCH SEPARATION (03) LATCH-STRIKER SEPARATION (04) STRIKER-PILLAR SEPARATION (05) BODY DISTORTION (06) COMBINATION OF ABOVE (CIRCLE EACH) (07) OPENED, REASON UNKNOWN (11) VAN RIGHT-REAR DOOR OPENED (ANY MECHANISM)
55	(98) NOT APPLICABLE (NO DOOR) (99) UNKNOWN
<u>@</u>	-FRONT S S S S S S S S S S S S S S S S S S S
57 <u>Ø</u> 58	DOORS JAMMED CLOSED-  USE CODES:  (0) NO (1) YES
<b>S</b> 59	(8) NOT APPLICABLE (NO DOOR) (9) UNKNOWN
8 = 0	-REAR
<b>8</b> 61	
<b>%</b>   <sub>α</sub>	VAN REAR DOOR TYPE  (0) VAN, NO REAR DOOR (1) TRACK (SLIDING) - RIGHT SIDE (2) SINGLE-HINGED - RIGHT SIDE (3) DOUBLE-HINGED - RIGHT SIDE (4) TRACK (SLIDING) - RIGHT & LEFT SIDE (5) SINGLE-HINGED - RIGHT & LEFT SIDE (6) DOUBLE-HINGED - RIGHT & LEFT SIDE (7) TRACK AND HINGED COMBINATION (8) NOT APPLICABLE (NOT A VAN) (9) UNKNOWN

		EXTERIOR DAMAGE	ED-5
WINDSHIELD DAMAGE		WINDSHIELD MARK ON CASE VEHICLE:	
WINDSHIELD CRACKED  (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	70		l ITB
WINDSHIELD BROKEN (PLASTIC INTERLAYER TORN)  (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	$ \underline{\Phi} $	SAFTY GE FLO-	416
CRACKED OR BROKEN BY OCCUPANT CONTACT  (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	<u>Q</u>	WINDSHIELD CODE  (97) DESCRIBED BUT NOT CODED  (98) NOT APPLICABLE (NO WINDSHIELD)	977
(0) NONE (1) 1 - 20% (2) 21 - 40 (3) 41 - 60 (4) 61 - 80 (5) 81 - 99 (6) TOTAL (7) SEPARATED, AMOUNT	<u>\$\vec{\mathbb{Q}}{\sigma}\$</u>	(99) UNKNOWN  ROOF  DID T-ROOF/SUN ROOF OPEN DURING COLLISION?  (0) NO (1) YES	L
UNKNOWN (8) NOT APPLICABLE (9) UNKNOWN		(8) NOT APPLICABLE (NOT A T-ROOF OR SUN ROOF) (9) UNKNOWN	76

LOCATE AREA OF WINDSHIELD INTEREST OR DAMAGE WITH DIMENSIONS (VERTICAL & HORIZONTAL) ON THIS DIAGRAM OF THE WINDSHIELD AS VIEWED FROM <u>INSIDE</u>.



<u>68</u>


<u>83</u>

68 R

Duplicate columns 1-8 Module S C Format from the previous card. 9 10	0 1	STEERING WHEEL AND COLUMN	SC-1
STEERING WHEEL RIM DAMAGE  (0) NONE (1) DEFORMED SLIGHTLY (2) SEVERELY BENT (3) BROKEN (9) UNKNOWN  NUMBER OF	<b>Q</b> <sub>13</sub>	STEERING WHEEL POSITION AT TIME OF COLLISION  IN WHAT O'CLOCK POSITION WAS THE NORMAL TOP OF THE WHEEL POINTED WHEN THE COLLISION OCCURRED?  EXAMPLES  O'CLOCK = 1 2  O'CLOCK = 1 2	
STEERING WHEEL SPOKES (9) UNKNOWN	4	(NORMAL STRAIGHT AMEAD) O'CLOCK - 99	
STEERING WHL SPOKE DAMAGE  (0) NONE (1) DEFORMED SLIGHTLY (2) SEVERELY BENT (3) BROKEN (9) UNKNOWN	15	STEERING WHEEL ENERGY ABSORBING DEVICE  (1) EXAMPLES:  BARRACUDA, 70 - 74 CHALLENGER, 70 - 74 CAPRI, 71 - 77	
STEERING COLUMN OPTIONS		(2) EXAMPLES:  CMNI, 79 -  HORIZON, 79 -	
TILT FEATURE  (0) NOT EQUIPPED (1) YES, EQUIPPED, UNK POSITION (2) UP (3) MIDDLE (4) LOWER (9) UNKNOWN IF EQUIPPED	<u>2</u>	TYPE OF DEVICE  (0) NONE (1) CONVOLUTED OR MESH CYLINDER (2) DEEP DISH STEERING WHEEL (7) OTHER:	8 19
SWING-AWAY FEATURE  (0) NOT EQUIPPED  (1) YES, EQUIPPED  (9) UNKNOWN IF EQUIPPED	<u></u>	ORIGINAL DIMENSION (mm)  A:  DAMAGE DIMENSION (mm)  B:  DIFFERENCE (mm)	
TELESCOPING FEATURE  (0) NOT EQUIPPED  (1) YES, EQUIPPED  (9) UNKNOWN IF EQUIPPED	18	A - B  (888) NOT COLLECTED  (991) NOT MEASURED/NO APPARENT COMPRESSION  (992) COMPRESSED, AMOUNT UNKNOWN  (993) DEVICE EXTENDED  (997) UNABLE TO MEASURE  (998) NOT APPLICABLE (NOT EQUIPPED)  (999) UNKNOWN	8 8

		STEERING WHEEL AND COLUMN SC-2
STEERING COLUMN ENERGY ABSORBING DEVICE		STEERING WHEEL (CONTINUED)
TYPE OF DEVICE * (IF 27 OR 28)		STEERING WHEEL HUB DAMAGE
(00) NOT EQUIPPED (88) NOT COLLECTED (99) UNKNOWN	8 8	(0) NONE (1) OCCUPANT CONTACT (2) AIRBAG 33
ORIGINAL LENGTH (mm) C:		(3) OTHER (9) UNKNOWN
COMPRESSED LENGTH (mm)		
D:		
BRACKET DEFLECTION (IF CODE 36, 48, OR 49 ABOVE) OR		
COMPRESSION (OR EXTRUSION) (mm)		
C - D (OR E) (TOLERANCE: ±10)		
(888) NOT COLLECTED (991) NOT MEASURED/NO APPARENT COMPRESSION (992) COMPRESSED, AMOUNT UNKNOWN (993) DEVICE EXTENDED (997) UNABLE TO BE MEASURED (998) NOT APPLICABLE (NOT EQUIPPED) (999) UNKNOWN	8 8 8 25 27	
* (ADD A & B FOR TOTAL COMPRESSION)		
SHEAR CAPSULE SEPARATION (mm)		
S (USE AVG. OF LEFT & RIGHT CAPSULES.)		
RT:		
(888) NOT COLLECTED (991) NOT MEASURED/NO APPARENT SEPARATION (992) SEPARATED, AMOUNT UNKNOWN (997) UNABLE TO BE MEASURED (998) NOT APPLICABLE (NOT EQUIPPED) (999) UNKNOWN	8 8 8	•
COLUMN VERTICAL ROTATION		
<ul><li>(0) NO APPARENT ROTATION</li><li>(1) UPWARD APPARENT ROTATION</li><li>(2) DOWNWARD APPARENT ROTATION</li><li>(9) UNKNOWN</li></ul>	<u>v</u>	
COLUMN LATERAL ROTATION	m	
(0) NO APPARENT ROTATION (1) LEFT APPARENT ROTATION (2) RIGHT APPARENT ROTATION (9) UNKNOWN	<u>z</u>	

							INTRU	JSIOI	N IT-1
				(All Meas	urements Are in	Centimet	ers)		D:
Location of Intrusion	Intruded Comp	ponent	Comparise Value	on _	Intruded Value	=	Intrusion		Dominant Crush Direction
/3	Floor par		31	-	-21	=	10		υp
	(buckled)			_	_	=			
				_	-	=		T	
****				-	_	=			
				_	-	=			
					_	=			
				_	-	8			
				-	-	=			
					<del>-</del>	=			
				_	-	=			
					_	=			<u>.</u>
				_	-	=			
					-	=			
			· · · · · · · · · · · · · · · · · · ·	-	-	=			
-				_	-	=			
					-	=			
		occi	UPANT CO	ONTAC	T WORKSHE	ET			
Contact	Component N	upant o. if F own if	Body Region Known		Supporting	Physical	l Evidence		Confidence Level of Contact Point
Α									
В									
С									
D									
E							•		
F									
G									
Н									
ı				<del></del>					
J									



# INTRUSION IT-3

# CODES FOR COLUMN B, OCCUPANT SPACE NUMBER

OCCUPANT SPACE NUMBER IS A TWO-DIGIT CODE. THE USE OF THE CODE IS DETERMINED BY THE VEHICLE SEAT CONFIGURATION AT THE TIME OF THE ACCIDENT.

### **FIRST DIGIT**

THE FIRST DIGIT (LEFT DIGIT) DENOTES THE SEAT ROW, WITH CODE VALUES FROM 1 TO 5.

### SECOND DIGIT

THE SECOND DIGIT (RIGHT DIGIT) DENOTES THE POSITION ON THE SEAT AND, IN SOME INSTANCES, THE WIDTH OF THE SEAT.

1	(1)	LEFT	(3)	RIGHT	•••••		INDIVIDU	JAL SEAT
(	(1)	LEFT	(2)	CENTER	(3)	RIGHT	BENCH:	FULL WIDTH 3 PASSENGER
•	(1)	LEFT		LEFT CENTER		RIGHT (3) RIGHTCENTER	BENCH:	FULL WIDTH 4 PASSENGER
(	(1)	LEFT	(2)	CENTER		RIGHT &	BENCH:	PARTIAL WIDTH, LEFT
(		LEFT & SPACE	(2)	CENTER		RIGHT &SPACE	BENCH:	PARTIAL WIDTH, CENTERED
(	4)	ENTIRE V	/EH	ICLE WIDTH			CARGO	AREA

### **EXAMPLES**

THE TWO FIGURES BELOW PROVIDE EXAMPLES OF THE OCCUPANT SPACE NUMBER.

PASSENGER CAR 5 PASSENGERS

VAN 12 PASSENGER CAPACITY

X	X	11			13	
x x	X			21	22	25
x x	X			31	32	35
x x	x x	41	42	46	43	

# CODES FOR COLUMN F, MEASUREMENT AXIS

- (X) X-AXIS (FORE & AFT)
- (Y) Y-AXIS (LATERAL)
- (Z) Z-AXIS (VERTICAL)

# CODES FOR COLUMNS G, H, I & J, OCCUPANT & INJURY NUMBERS

OCCUPANT	INJURY	•
NUMBER	NUMBER	CONTACT
(00)	(00)	NO CONTACT
(##)	(00)	CONTACT, NO INJURY
(97)	(99)	CONTACT, OCCUPANT UNKNOWN, INJURY UNKNOWN
(99)	(00) OR (99)	UNKNOWN IF CONTACT

# INTRUSION IT-4

### CODES FOR COLUMN C, INTRUDING COMPONENT OR OBJECT

NOTE: <u>DO NOT</u> CODE OBJECTS OTHER THAN COMPONENTS OF CASE VEHICLE.

### INDIVIDUAL COMPONENT

## GROUPED FOR MASSIVE INTRUSION INTO AN OCCUPANT SPACE

#### **INTERNAL**

- (01) INSTRUMENT PANEL
- (02) FIRE WALL
- (03) TOE PAN
- (04) FLOOR PAN
- (05) STEERING COLUMN
- (06) WINDSHIELD
- (07) WINDSHIELD HEADER
- (08) A-PILLAR
- (09) DOOR PANEL OR SIDE PANEL
- (10) WINDOW FRAME
- (11) B-PILLAR
- (12) C-PILLAR
- (13) D-PILLAR
- (14) ROOF SIDE RAILS
- (15) ROOF OR CONVERTIBLE TOP
- (16) BACKLIGHT HEADER
- (17) FRONT SEAT-BACK SURFACE/ SEAT-BACK BACK SURFACE
- (18) SECOND SEAT-BACK SURFACE SEAT-BACK BACK SURFACE
- (19) THIRD SEAT-BACK SURFACE SEAT-BACK BACK SURFACE
- (20) FOURTH SEAT-BACK SURFACE SEAT-BACK BACK SURFACE
- (21) FIFTH SEAT-BACK SURFACE SEAT-BACK BACK SURFACE
- (22) BACK PANEL/BACK DOOR SURFACE
- (23) SEAT CUSHION SURFACE/EDGE
- (24) CONSOLE
- (25) OTHER (DESCRIBE)
- (26) UNKNOWN INTERNAL SURFACES
- (28) TRANSMISSION TUNNEL (HUMP)
- (29) SIDE FOOTWELL PANEL (KICKPANEL)
- (30) SILL

### **EXTERNAL**

- (43) HOOD
- (44) OBJECT EXTERNAL TO PASSENGER COMPARTMENT BUT PART OF CASE VEHICLE
- (45) OUTSIDE SURFACE OF CASE VEHICLE
- (46) OTHER (E.G. SPARE TIRE, JACK. DESCRIBE.)
- (49) UNKNOWN EXTERNAL OBJECT

INTRUDED INTO A SINGLE OCCUPANT SPACE.

USE ONLY IF ALL THESE COMPONENTS

- (50)WINDSHIELD HEADER A-PILLAR
  - ROOF SIDE RAIL
- (51)INSTRUMENT PANEL A-PILLAR DOOR PANEL
- (52)INSTRUMENT PANEL A-PILLAR WINDSHIELD HEADER
- (53)DOOR PANEL B-PILLAR ROOF RAIL
- (54)DOOR PANEL A-PILLAR ROOF BAIL
- (55)INSTRUMENT PANEL FLOOR PAN A-PILLAR DOOR FRAME
- (56)ROOF RAIL A-PILLAR B-PILLAR WINDOW FRAME
- (57)ROOF RAIL A-PILLAR B-PILLAR C-PILLAR DOOR PANEL
- (58)ROOF ROOF RAIL WINDOW FRAME DOOR PANEL
- (59)BACKLIGHT HEADER ROOF C-PILLAR THIRD SEAT-BACK

- (60)ROOF
  ROOF RAIL
  A-PILLAR
  B-PILLAR
  C-PILLAR
  WINDOW FRAME
  DOOR PANEL
  FLOOR PAN
- (61)INSTRUMENT PANEL TOE PAN WINDSHIELD HEADER A-PILLAR ROOF RAIL WINDOW FRAME DOOR PANEL ROOF
- (62)ROOF
  ROOF RAIL
  C-PILLAR
  WINDOW FRAME
  FLOOR PAN
  SECOND SEAT
  DOOR PANEL
- (63)ROOF RAIL
  ROOF
  B-PILLAR
  WINDOW FRAME
  FLOOR PAN
  DOOR PANEL
  SECOND SEAT
  FRONT SEAT
- (64)ROOF RAIL
  ROOF OR CONVERTIBLE TOP
  A-PILLAR
  B-PILLAR
  WINDOW FRAME
  WINDOW HEADER
- (65)WINDSHIELD WINDSHIELD HEADER ROOF SIDE RAIL
- (66)WINDSHIELD WINDSHIELD HEADER A-PILLAR

(98)NOT APPLICABLE

(99)UNKNOWN

Duplicate columns 1-8 from the previous card.  Module 1 9	T Format 0	1 12			INTE	RUSION	IT-5			
WAS THERE OCCUPANT COMPA  (0) NO DO NOT ANSWER NEXT OF  (1) YES ANSWER NEXT QUESTION  (9) UNKNOWN SKIP PAGE	UESTION. <u>SKIP PAG</u>	1	1 W		ION CATAST COMPLETE PA SKIP PAGE.		Ø			
Duplicate columns 1-8 from the previous card.  NOTE: Each line in the table below is a separate record (card).  Duplicate columns 1 - 12 for each completed line.  INTRUSIONS CODE INTRUSIONS IN THIS ORDER: LEFT TO RIGHT ON ROW; FRONT TO BACK IN VEHICLES.  CODES FOR B, F, G, H, I, J ON PAGE IT-3  CODES FOR C ON PAGE IT-4  OCCUPANT CONTACT AND INJURY										
A B C INTRUDING AS INTRUSION OCC. COMPONENT EV	D E SOC. MAXIMUM	F MAXIMUM INTRUSION		· H OCCUPANT NUMBER	I INJURY NUMBER	J OCCUPANT NUMBER	K INJURY NUMBER			
13-14 15-16 17-18	19 20-21	22-23	24-25	26-27	28-29	30-31	32-33			
o 1 13 04	Ι ΦΦ	$\Phi$	10	$\Omega \Omega$	$Q \Phi$	00	<u>Ø</u> <u>Ø</u>			
02				<u> </u>						
03										
04			<del></del>							
05										
06				. — —						
0 7 NOTE: USE ADDITIONAL PAGE IF MORE THAN	17 INTRUSIONS		-			<u> </u>				
Duplicate columns 1-8 Module 1 9		3 12			·					
NOTE: IF NO SIDE DOOR INTRUSION, SKIP REMAINDER OF PAGE. SIDE DOOR INTRUSION RESULTED FROM	IF DA DOO! INTRU NUMB	R INTRUS SION	DOOR COSION, CODI		RESULTE ENT AGED ONENT 2	ED IN INCRE  CODES FOR COMPON				
INTRUSION   NUMBER   CAUSE   CODES   FOR CAUSE:	A	- -	- - - -		29 33 37	(0) NONE (1) A-PILLAR (2) B-PILLAR (3) C-PILLAR (4) LATCH/STF (5) HINGES (7) OTHER: (8) NOT APPLI (9) UNKNOWN	RIKER — CABLE			

Duplicate columns 1-8 from the previous card.

Module <u>I</u> <u>T</u> Format <u>0</u> <u>2</u> 11 12

INTRUSION

IT-6

NOTE: Each line in the table below is a separate record (card).

Duplicate columns 1 - 12 for each completed line.

- ADDITIONAL PAGE -

INTRUSIONS CODE INTRUSIONS IN THIS ORDER: LEFT TO RIGHT ON ROW; FRONT TO BACK IN VEHICLES.

CODES FOR B, F, G, H, I, J ON PAGE IT-3

CODES FOR C ON PAGE IT-4

OCCUPANT CONTACT AND INJURY

A	В	С	D	E	F	G	н	. 1	J	K
INTRUSION	OCC. SPACE NO.	INTRUDING COMPONENT OR OBJECT		INTRUSION	MAXIMUM INTRUSION Y AXIS (cm)		OCCUPANT NUMBER	INJURY NUMBER	OCCUPANT NUMBER	INJURY
13-14	15-16	17-18	19	20-21	22-23	24-25	26-27	28-29	30-31	32-33
08										
09										
10										
11								<del></del>		
12.										
13			_	<del></del>					<del></del>	
1 4										
1 5					<del></del>					
1 6				<del></del>						
17										
18		<del></del>					<del></del>			
19									<del></del>	
20										
21			.—							
22			_							
23										
24			_							
2 5										

Duplicate columns 1-8 from the previous card.	Modu	ie <u>  D</u>	Format <u>0</u> <u>1</u> 12	. IN	TERIOR DAMAGE I	D-1
со	(1	)) NO ) YES 3) NO, and	OCCUPANT CONTACT	(4) YES, and (8) NOT APPL (9) UNKNOWN		
SIDES FRONT DOOR FRONT HARDWARE FRONT ARMREST FRONT GLASS REAR DOOR AREA REAR HARDWARE REAR ARMREST REAR GLASS Petachable ** ROOF SIDE RAIL MISSING CAC B-PILLAR C-PILLAR D-PILLAR HEADLINING ROOF STRUCTURE T-ROOF/SUN ROOF OTHER: **	LEFT 0   20   15 4   17 1   19 0   21 0   22 0   25		FRONT FOOT CONTROLS  IGNITION KEYS  REAR VIEW MIRROR  SUNVISOR/FITTINGS  (5) LEFT SIDE ONLY (6) RIGHT SIDE ONLY (7) BOTH SIDES  WINDSHIELD TOP MOLDINGS  LEFT A-PILLAR (UPPER OR LOWER)  RIGHT A-PILLAR (UPPER OR LOWER)  CENTER CONSOLE  TRANSMISSION SELECTOR LEVER  RIM, HORN, SPOKE		INSTRUMENT PANEL UPPER PANEL MID PANEL LOWER PANEL ASHTRAY CONTROL KNOBS & LEVERS GLOVE COMPARTMENT AREA INSTRUMENTS PARKING BRAKE RELEASE PARKING BRAKE PEDAL A/C OR UPPER VENT OUTLETS HEATER OR A/C DUCTS RADIO OTHER: *  REAR WINDOW WINDOW HEADER  CONSOLES VERTICAL	
			·		ROOF	Ø 71

<sup>\*</sup> MORE THAN ONE ITEM MAY BE NOTED.

Duplicate columns 1-8 from the previous card.  Module S T		2 1 12	SEATS		ST-1
FRONT SEAT  TYPE OF FRONT SEAT  (00) NO SEAT  (01) STANDARD BENCH (02) SPLIT BACK, 50-50 (03) SPLIT BACK, DRIVER WIDE (04) SPLIT BACK, PASS. WIDE (05) BUCKET (06) CAPTAIN'S CHAIR (07) INDIV. BENCH, 50-50 (08) INDIV. BENCH, DRIVER WIDE (09) INDIV. BENCH, PASS. WIDE (97) OTHER: (99) UNKNOWN  TYPE OF SEAT MOUNT (1) STANDARD (2) PEDESTAL (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN  SWIVEL MECHANISM EQUIPPED (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN  ORIGINAL EQUIPMENT SEATS (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN  CONTACT OF SEAT BY REAR OCCUPANT (0) NO (1) YES (8) NOT APPLICABLE	DRIVER  0 5 13 14  17  17  19 19 21 21 22	PASSENTR  05 15 16	FRONT SEAT-BACK  SEAT-BACK TYPE  (1) FORWARD FOLDING (2) RIGID (3) RECLINING (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN  SEAT-BACK LOCK TYPE (0) NONE (1) MANUAL (2) INERTIA (3) POWER (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN  LOCKS HELD (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN  RECLINER MECHANISM HELD (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	32 L 34 L 36	31 33 35
(9) UNKNOWN  FRONT SEAT DAMAGE  (0) NONE (1) BACKREST ONLY DAMAGED (2) CUSHION ONLY DAMAGED (3) BACKREST & CUSHION DAMAGED (8) NOT APPLICABLE (9) UNKNOWN	<u></u>	<b>1</b> 25	HEAD RESTRAINT HEAD RESTRAINT TYPE (0) NONE (1) ADJUSTABLE (2) INTEGRAL (3) NOT INTEGRAL, BUT CANNOT BE REMOVED (7) OTHER:	38	39
CENTER ARMREST DAMAGED  (0) NO (1) YES (7) EQUIPPED, DAMAGE UNKNOWN (8) NOT APPLICABLE (NO CENTER ARMREST) (9) UNKNOWN IF EQUIPPED	٩	Ď,	(8) NOT APPLICABLE (9) UNKNOWN  REMOVED PRE-CRASH (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN  ADJUSTMENT AT CRASH	<b>Q</b>	ر ر
FRONT SEAT ROTATION  (0) NONE APPARENT (1) FORWARD APPARENT (2) REARWARD APPARENT (3) LEFT APPARENT (4) RIGHT APPARENT (5) MULTIPLE ROTATIONS SPECIFY (8) NOT APPLICABLE (9) UNKNOWN	<u>Ø</u>	<u>۾</u>	(1) UP (2) DOWN (8) NOT APPLICABLE (9) UNKNOWN  HEAD RESTRAINT DAMAGE (0) NONE (1) DAMAGED BUT NOT SEPARATED (2) SEPARATED (8) NOT APPLICABLE (9) UNKNOWN		

			Sı	EATS	ST-2
FRONT SEAT ADJUSTMENT	DRIVER	PASSENT	SECOND SEAT (CONT.)		
SEAT ADJUSTMENT TYPE  (0) NONE (RIGID) (1) MANUAL (2) POWER (7) OTHER: (8) NOT APPLICABLE (NO SEAT) (9) UNKNOWN  ADJUSTMENT PROVIDED	<u>2</u> 3	<del> </del>   2	CENTER ARMREST DAMAGED  (0) NO (1) YES (7) EQUIPPED, DAMAGE UNKNOWN (8) NOT APPLICABLE (NO CENTER ARMREST) (9) UNKNOWN IF EQUIPPED		8
(1) 2-WAY (2) 4-WAY (3) 6-WAY (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN	48	49	SECOND SEAT-BACK LOCKS	LEFT	Rіснт
SEAT ADJUSTER DAMAGE  (0) NONE  (1) CHUCKING (FREE PLAY)  (2) DEFORMED (RELEASED/JAMMED)  (3) SEPARATED  (7) OTHER:  (8) NOT APPLICABLE  (9) UNKNOWN	<u>©</u>	<b>1 2 5</b> 1	FOR THE FOLLOWING, USE:  (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN  LEFT OR CENTER, EQUIPPED		Ø
SEAT ADJUSTER SEPARATION  (0) NONE  (1) SEPARATED AT FLOOR  (2) SEPARATION OF ADJUSTER  (3) SEPARATED AT SEAT  (8) NOT APPLICABLE  (9) UNKNOWN	52	<u>8</u>	LEFT OR CENTER, EQUIPPED  (3) SEAT FOLDED DOWN  RIGHT, EQUIPPED		9831   8
PRE-CRASH POSITION  (1) FORWARD (2) MIDDLE (3) REARWARD (8) NOT APPLICABLE (9) UNKNOWN	3	<u>2</u>	RIGHT, HELD  (3) SEAT FOLDED DOWN  THIRD SEAT	67	<b>₩</b>
SECOND SEAT TYPE OF SECOND SEAT	LEFT	RIGHT	EQUIPPED	8	0 2
(0) NONE (1) NON-FOLDING (2) FOLDING (3) CAPTAIN'S CHAIR (4) JUMP SEAT	56	57	BACKREST DAMAGED  CUSHION DAMAGED	71 00 73	Ø 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
(5) INTEGRAL CHILD SEAT (6) LUGGAGE AREA ACCESS PANEL (9) UNKNOWN  SECOND SEAT DAMAGE (0) NONE (1) BACKREST ONLY (DAMAGED OR LOOSENED) (2) CUSHION ONLY (DAMAGED OR LOOSENED) (3) BACKREST & CUSHION (DAMAGED OR LOOSENED) (4) INTEGRAL CHILD SEAT (PRIORITY CODE) (5) LUGGAGE AREA ACCESS PANEL (DAMAGED OR LOOSENED) (8) NOT APPLICABLE (9) UNKNOWN	<b>⊘</b> ss	59	VEHICLE EQUIPPED WITH REAR HEAD RESTRAINTS  (0) NOT EQUIPPED (OR REMOVED) (1) EQUIPPED (2) EQUIPPED & DAMAGED (8) NOT APPLICABLE (NO REAR SEAT) (9) UNKNOWN  Applies to any rear-seat position		<u>D</u>

Duplicate columns 1-8 Module A B Format 0 11 11	12	AIRBAG .	AB-
DRIVER SIDE		PASSENGER SIDE	: :
LOCATION OF AIRBAG		LOCATION OF AIRBAG	
STEERING WHEEL		INSTRUMENT PANEL (GLOVE BOX)	
EQUIPPED	:	EQUIPPED	
(0) NO	1	(0) NO	
(1) YES (4) PRIOR DEPLOYMENT	13	(1) YES (4) PRIOR DEPLOYMENT	1
NOT REINSTALLED  (9) UNKNOWN IF AIRBAG EQUIPPED		NOT REINSTALLED (9) UNKNOWN IF AIRBAG EQUIPPED	
		• •	
DEPLOYED		DEPLOYED	
(0) NO		(0) NO ·	1
(1) YES (2) PARTIAL/IMPROPER DEPLOYMENT	+	(1) YES (2) PARTIAL/IMPROPER DEPLOYMENT	17
(8) NOT APPLICABLE (NO AIRBAG)		(8) NOT APPLICABLE (NO AIRBAG)	
(9) UNKNOWN		(9) UNKNOWN	
CONDITION OF AIRBAG		CONDITION OF AIRBAG	
STEERING WHEEL			
		INSTRUMENT PANEL (GLOVE BOX)	
(0) NO DAMAGE (2) SPLIT OR TORN	0	(0) NO DAMAGE (2) SPLIT OR TORN	
(3) CUT DURING CRASH (4) BURNED/MELTED	15	(3) CUT DURING CRASH (4) BURNED/MELTED	7
(5) CUT POST CRASH (6) OTHER		(5) CUT POST CRASH (6) OTHER	
(7) DAMAGED, CONDITION UNKNOWN (8) NOT APPLICABLE (NOT EQUIPPEDNOT DEPLOYED)		(7) DAMAGED, CONDITION UNKNOWN (8) NOT APPLICABLE (NOT EQUIPPEDNOT DEPLOYED)	
(9) UNKNOWN IF EQUIPPED OR CONDITION		(9) UNKNOWN IF EQUIPPED OR CONDITION	
DRIVER SIDE		PASSENGER SIDE	
AIRBAG		AIRBAG	
STEERING WHEEL		INSTRUMENT PANEL (GLOVE BOX)	
TETHER	_	TETHER	L
(0) NO (1) YES	$\Psi$	(0) NO (1) YES	l
(6) OTHER (7) UNKNOWN IF TETHERED	19	(6) OTHER	21
(8) NOT APPLICABLE (NO AIRBAG)		(B) NOT APPLICABLE (NO AIRBAG)	
(9) UNKNOWN IF AIRBAG EQUIPPED		(9) UNKNOWN IF AIRBAG EQUIPPED	
MARKED BY CONTACT		MARKED BY CONTACT	
(0) NO (1) YES	<b>O</b>	(0) NO	
(8) NOT APPLICABLE	20	(1) YES (8) NOT APPLICABLE	22
(NO AIRBAG)		(NO AIRBAG)	

	AIRBAG AB-2
AIRBAG NUMBER ON DE	RIVER SIDE:
	NOTE AND DESCRIBE ANY AIRBAG CONTACT OR DAMAGE ON DIAGRAM BELOW:
	Blood drops
AIRBAG NUMBER ON F	PASSENGER SIDE:
	NOTE AND DESCRIBE ANY AIRBAG CONTACT OR DAMAGE ON DIAGRAM BELOW:
Non	arent

### NOTE TO THE INVESTIGATOR:

THE FOLLOWING TWO SECTIONS,

OCCUPANT INFORMATION AND INJURY CLASSIFICATION,

ARE TO BE FILLED IN

FOR EACH CASE VEHICLE OCCUPANT,

WHETHER INJURED OR NOT.

IF THERE IS MORE THAN ONE OCCUPANT,
USE ADDITIONAL COPIES
OF PAGES OC-1, OC-2, OC-3,
AND IC-2 TO DESCRIBE THEM
AND ATTACH THE COPIES TO THIS REPORT.


Duplicate columns 1-8 from the previous card.  Module O C Format 0 11		OCCUPANT INFORMATION	OC-1
OCCUPANT IDENTIFICATION OCCUPANT NUMBER  ROLE OF OCCUPANT AT 1ST IMPACT  (1) MOTOR VEHICLE DRIVER (2) MOTOR VEHICLE PASSENGER (NOT DRIVER) (9) UNKNOWN	13 14	PHYSICAL DESCRIPTION  AGE IN YEARS  (00) LESS THAN 1 YEAR  (98) 98 YEARS OR OLDER  (99) UNKNOWN  AGE IN MONTHS  (00) LESS THAN 1 MONTH  (25) 25 MONTHS OR OLDER  (99) UNKNOWN	$\frac{18}{20}$ $\frac{2}{21}$ $\frac{2}{22}$ $\frac{5}{22}$
OCCUPANT POSITION  ROW LOCATION  (1) FRONT (2) SECOND (3) THIRD (4) FOURTH (7) OTHER: (8) EXTERNAL TO PASSENGER COMPARTMENT (E.G. BED OF PICKUP) (9) UNKNOWN	16	MASS (kg)  (999) UNKNOWN  HEIGHT (cm)  (999) UNKNOWN  SEX  (1) MALE  (2) FEMALE  (9) UNKNOWN	$\frac{0}{24} \frac{32}{25} \frac{2}{26}$ $\frac{1}{27} \frac{7}{28} \frac{8}{29}$ $\frac{1}{30}$
LATERAL LOCATION  (1) LEFT (2) LEFT CENTER (3) CENTER (4) RIGHT CENTER (5) RIGHT (6) ALL (LYING ON SEAT) (8) EXTERNAL TO PASSENGER COMPARTMENT (9) UNKNOWN	17	MEDICAL CONDITIONS  TREATMENT/MORTALITY  (00) NONE  (01) FIRST AID AT SCENE  (02) TREATED AT HOSPITAL/CLINIC  BUT NOT ADMITTED  (03) HOSPITALIZED FOR OBSERVATION  LESS THAN 24 HOURS  (04) HOSPITALIZED OVER 24 HOURS  OR FOR SIGNIFICANT TREATMENT  (05) FATAL, DEAD AT SCENE  (06) FATAL, DOA	<u>Q</u> <u>2</u>
POSTURE  (10) SITTING ON SEAT (11) SITTING ON SEAT IN ABNORMAL POSITION (E.G. FEET ON DASH, SIDEWAYS) (12) SITTING ON CONSOLE (20) ON LAP OR IN ARMS (30) STANDING ON SEAT (40) STANDING ON FLOOR (47) STANDING, EXTERNAL TO PASSENGER COMPARTMENT (50) IN BASSINET (60) IN CHILD SEAT (65) IN CHILD HARNESS (70) LYING ON SEAT (80) LYING/SITTING ON PASSENGER FLOOR (83) LYING/SITTING ON OTHER OBJECT IN PASSENGER COMPARTMENT: (85) ON CARGO FLOOR/FOLDED SEAT-BACK	18 10	(07) FATAL, DEAD WITHIN 24 HOURS (08) FATAL, DEAD 24 HOURS TO 31 DAYS LATER (09) FATAL, DEAD 31 DAYS TO 1 YEAR LATER (10) FATAL DEAD WITHIN UNKNOWN PERIOD (99) UNKNOWN  INJURY SEVERITY SCORE (ISS) (99) UNKNOWN  NON-IMPACT MED. CONDITIONS (0) NONE (1) YES, TIME & TYPE UNKNOWN (2) PRE-CRASH FATAL (CLINICAL DEATH AT WHEEL) (3) PRE-CRASH NON-FATAL (E.G. PRIOR INJURY, STROKE) (4) PREGNANT (5) POST-CRASH FATAL (DROWNING) (6) POST-CRASH NON-FATAL INJURY	$\frac{\cancel{O}}{33} \frac{2}{34}$ $\cancel{O}$ 35
(87) LYING/SITTING, EXTERNAL TO PASSENGER COMPARTMENT  (97) OTHER: (99) UNKNOWN		(7) OTHER:	

		OCCUPANT INFORMATION	OC-2
MEDICAL CONDITIONS (CONT.)  POLICE INJURY SEVERITY CODE FOR THIS OCCUPANT  (0) O - NO INJURY (1) C - POSSIBLE INJURY (2) B - NON-INCAPACITATING (3) A - INCAPACITATING INJURY (4) K - FATAL (5) INJURED, SEVERITY UNKNOWN (6) DIED PRIOR TO IMPACT (7) NON-FATAL INJURY, SEVERITY UNKNOWN (9) UNKNOWN	35	CHILD SEAT TYPE  (00) NONE USED (01) YES, USED (02) INTEGRAL, Chrysler Mini-van (88) NOT APPLICABLE (ADULT OR OLDER CHILD) (99) UNKNOWN  CHILD SEAT MAKE/MODEL	8 8
RESTRAINT SYSTEM  (0) NONE (1) LAP BELT (2) SHOULDER HARNESS ONLY (3) BOTH LAP BELT & SHOULDER HARNESS (9) UNKNOWN  ACTIVE RESTRAINT SYSTEM USAGE  (0) NONE (AVAILABLE BUT NOT USED) (1) LAP BELT ONLY (2) SHOULDER HARNESS ONLY (3) BOTH LAP BELT & SHOULDER HARNESS (7) IMPROPER USAGE (8) NOT APPLICABLE (NONE AVAILABLE) (9) UNKNOWN  PASSIVE RESTRAINT SYSTEM  (0) NONE (1) AIRBAG INSTALLED (2) PASSIVE UPPER TORSO WITH KNEE BOLSTERS (3) PASSIVE UPPER TORSO WITH KNEE BOLSTERS (4) PASSIVE LAP & UPPER TORSO (5) AIRBAG INSTALLED & PASSIVE RESTRAINT (7) OTHER: (9) UNKNOWN  PASSIVE RESTRAINT SYSTEM USAGE  (0) SYSTEM DEFEATED (1) AIRBAG NOT DEPLOYED (2) AIRBAG DEPLOYED	333 333	EJECTION  DEGREE OF EJECTION  (0) NONE (1) PARTIAL (2) COMPLETE (7) EJECTED, DEGREE UNKNOWN (9) UNKNOWN IF EJECTED  AREA OF EJECTION  (01) WINDOW, LEFT SIDE (02) WINDOW, RIGHT SIDE (03) WINDOW, REAR (04) DOOR, LEFT SIDE (05) DOOR, RIGHT SIDE (06) DOOR, REAR OR TAILGATE (07) WINDSHIELD (08) ROOF OR OPEN CONVERTIBLE OR FROM EXTERNAL AREA (96) EJECTED AREA UNKNOWN (97) OTHER AREA: (98) NOT APPLICABLE (NOT EJECTED) (99) UNKNOWN IF EJECTED	9 3 45
(3) AIRBAG NOT REINSTALLED (4) PASSIVE UPPER TORSO USED (5) PASSIVE LAP & UPPER TORSO USED (6) SYSTEM USED IN MANUAL MODE (7) IMPROPER USAGE (8) NOT APPLICABLE (NOT ORIGINALLY EQUIPPED) (9) UNKNOWN	40	HEAD RESTRAINT HEAD RESTRAINT AVAILABLE FOR THIS POSITION  (0) NOT EQUIPPED OR REMOVED (1) EQUIPPED (9) UNKNOWN	<u>L</u>

# OCCUPANT EYEWEAR (0) NONE (1) GLASSES (2) CONTACTS (3) BOTH GLASSES AND CONTACTS (4) OTHER (8) NOT APPLICABLE (9) UNKNOWN OCCUPANT INFORMATION (0) INTERVIEW (1) HOSPITAL (2) ADTOPSY (3) POLICE (4) OTHER (5) LAY CORONER/EXTERNAL EXAM (7) COMBINATION OF ABOVE (CIRCLE) (8) NOT APPLICABLE (9) UNKNOWN

# OCCUPANT INFORMATION OC-4

# INDICATE LOCATION OF INJURIES.



Duplicate columns 1-8 from the previous card.

Module <u>I</u> <u>C</u> Format <u>0</u> <u>1</u> 12

INJURY CLASSIFICATION IC-1

NOTE: Each line in the table below is a separate record (card). Duplicate columns 1 - 12 for each completed line.


INJURY CLASSIFICATION	

						PRIM	ARY (	OIC		A	ssoc	IATE	OIC	!	COMMENTS
OCCUPANT NUMBER	INJURY NUMBER	PROBAB START V IN 1ST C	ILITY (HORI VITH MOST I CONTACT AF	N ORDER OF ZONTALLY) . PROBABLE REA COLUMN.	BODY REGION 1	ASPECT O	C NOISEL	SYSTEMORGAN 4	SEVERITY U	BODY REGION 1	ASPECT N	C NOIS31	SYSTEM/ORGAN 4	SEVERITY 5	
13-14	15-16	17-18	19-20	COMMENTS	21	22	23	24	25	26	27	28	29	30	
QL	$\Phi$	25			F	5	<u>_</u>	Ī	1	_		_	_	_	
1	02	<u>5a</u>			A	R	L	I	1	_	_	_	_	_	
	<u>@3</u>	98			B	I	<u>T</u> .	M	1	_	_		_	_	
	04	<u>53</u>			1			I							
	05	52			1			Ī			_				
	W 2						=			_	_		_		
		<u> </u>					-	— ,	<u> </u>	-	_	_	_	_	
					-	_	_		_	_	_		_	_	
نو					-		_	_	_	-	_			_	
"Occupant Number" for each line					-	_	_	_	_	-	_			_	
nber" fo					-	_	_	_	_	_	_		_	_	. <del>.</del>
ant Nur					_	_	_	_		_			_	_	
										_		_		_	
Duplicate					i	_	_								
					-	_	_						_		
					-	_	_			_	_		_		
					<u>:</u> —		_	_		-	_	_	_		
					:	_	_	_		-	_		_	_	
					-		_	_		-		_		_	
					_		_	_	_	_		_	_	_	

# INJURY CLASSIFICATION IC-2

# CODES FOR AREAS OF POSSIBLE OCCUPANT CONTACT

	OF PASSENGER COMPARTMENT	SIDES	
(10)	SUNVISOR, FITTING(S) &/OR TOP MOLDING	(20)	SURFACE OF SIDE INTERIOR
(12)	WINDSHIELD	(19)	HARDWARE ON SIDE OR DOOR
, ,		(13)	ARMREST ON SIDE OR DOOR
(05)	INCTOINGENT DANIEL (COCCIGIO ADEA LINUXIONAIL	7. *	
(05)	· · · · · · · · · · · · · · · · · · ·	(24)	COAT HOOK
(54)	UPPER INSTRUMENT PANEL (X)		
(55)	MIDDLE INSTRUMENT PANEL (Y)	(22)	WINDOW GLASS (SIDE)
(56)	LOWER INSTRUMENT PANEL (Z)	(21)	· · · · · · · · · · · · · · · · · · ·
	== ••	(£1)	THISOTI I THINKE (OIDE)
(81)	ASH TRAY (INSTRUMENT PANEL)		
(02)	GLOVE COMPARTMENT AREA	(26)	ROOF SIDE RAIL
(47)	AIRBAG (ACRS) COMPARTMENT DOOR/COVER	(14)	A-PILLAR
` '	, ,	, ,	B-PILLAR
<b>(</b>	OFFICATE INICTOLINECTE DANIEL	• •	
(57)		· · - /	C-PILLAR
(53)	PARCEL TRAY	(17)	D-PILL'AR
(48)	KNEE RESTRAINT		
(86)	VERTICAL CONSOLE	FLOOR	
(00)			5 00D
		(40)	
(28)	FOOT CONTROLS (INCL. PARKING BRAKE PEDAL)	(27)	CONSOLE ON FLOOR OR BETWEEN SEATS
		(44)	TRANSMISSION LEVER ON FLOOR OR CONSOLE
(09)	STEERING ASSEMBLY (SPECIFIC AREA UNKNOWN)		PARKING BRAKE HANDLE ON FLOOR OR CONSOLE
	'		
(65)	STEERING WHEEL	(28)	FOOT CONTROLS (INCL. PARKING BRAKE PEDAL)
(66)	STEERING WHEEL COLUMN	(91)	KICKPANEL
(59)	TRANSMISSION LEVER ON COLUMN		
\ <b>,</b>		Roof	
	HADDWADE ITEM (COECIEIO ADEA LIAMANOMO)		2005 02 0011152221 5 702
(03)	and the second s		ROOF OR CONVERTIBLE TOP
(82)	INSTRUMENT(S)	(10)	SUNVISOR, FITTING(S) &/OR TOP MOLDING
(83)	CONTROL KNOB(S) & LEVER(S) (FRONT)	(26)	ROOF SIDE RAIL
(84)	PARKING BRAKE HANDLE IN FRONT		COAT HOOK
		, ,	
(67)	IGNITION KEY	(18)	DOME LIGHT
(06)	MIRROR	(39)	BACKLIGHT HEADER
(04)	HEATER OR AIR CONDITIONING DUCTS	(68)	ROOF MOUNTED CONTROLS/CONSOLE
	AIR CONDITIONING OR VENTILATION OUTLET(S)		
(01)	, ,	(69)	ROLL BAR
(08)	RADIO (BUILT IN)		
(58)	ADD-ON TAPE DECK, RADIO, A/C	EXTERIO	OR SURFACE OF CASE VEHICLE
(68)	ROOF MOUNTED CONTROLS/CONSOLES	(37)	OUTSIDE SURFACE OF CASE VEHICLE
(55)		(0.)	
D			(SPECIFIC AREA UNKNOWN)
REAR		(35)	HOOD OF CASE VEHICLE
(88)	SURFACE OF REAR INTERIOR	(60)	EXTERIOR OF CASE VEHICLE (E.G.
	REAR WINDOW	(,	OUTSIDE MIRRORS, ANTENNA, TRIM)
			The state of the s
	REAR WINDOW HEADER	(62)	EXTERIOR SIDE ROOF RAIL OF CASE VEHICLE
(50)	REAR SEAT CUSHION & BACK	(63)	TRUNK LID OF CASE VEHICLE
		(64)	TIRES OF CASE VEHICLE
INTERIOR	R-GENERAL	(5.7	
		Prove	Canal Various a Boundary
	TRANSMISSION SELECTION LEVER (LOCATION UNK.)		CASE VEHICLE BOUNDARY
(59)	TRANSMISSION LEVER ON STEERING COLUMN	(36)	AREA EXTERIOR TO CAR (SPECIFIC AREA UNK.)
(44)	TRANSMISSION LEVER ON FLOOR OR CONSOLE	(70)	HOOD OF OTHER VEHICLE
	PARKING BRAKE HANDLE (LOCATION UNKNOWN)	(71)	OTHER VEHICLE EXTERIOR HARDWARE (E.G.
	· · · · · · · · · · · · · · · · · · ·	(71)	·
(84)	PARKING BRAKE HANDLE IN FRONT		OUTSIDE MIRRORS, ANTENNA, TRIM)
(85)	PARKING BRAKE HANDLE ON FLOOR OR CONSOLE	(73)	EXTERIOR SIDE ROOF RAIL OF OTHER VEHICLE
(28)	FOOT CONTROLS (INCL. PARKING BRAKE PEDAL)	(74)	HEADLIGHT OR FRONT GRILL OF OTHER VEH.
• •	•	(75)	TRUNK OF OTHER VEHICLE
(20)	EDONT CEAT-DACK(C)		
	FRONT SEAT-BACK(S)	(76)	OUTSIDE SURFACE OF OTHER VEHICLE
(51)	FRONT SEAT CUSHION	(77)	TIRES OF OTHER VEHICLE
(50)	REAR SEAT CUSHION & BACK	(78)	GROUND
	ARMREST ON SEAT	(79)	WATER
		· •	· · · · · <del>- · ·</del>
(89)	UNDER SEAT BOTTOM	(80)	EXTERIOR OBJECT (NOT VEHICLE, GROUND,
			OR WATER. PLEASE DESCRIBE.)
(33)	RESTRAINT SYSTEM HARDWARE		
	RESTRAINT SYSTEM WEBBING	PENETO	ATING OBJECTS
	AIR CUSHION SKIN (AIRBAG)		
	· · · · · · · · · · · · · · · · · · ·		OTHER VEHICLE
(47)	AIRBAG (ACRS) COMPARTMENT DOOR/COVER	(72)	OBJECTS (DESCRIBE)
(46)	AIRBAG GAS		
(48)		MISCELL	ANFOLIS
(30)		(00)	· · · · · · · · · · · · · · · · · · ·
(42)	CHILD SEAT RESTRAINTS	· (38)	OTHER (E.G. FIRE. DESCRIBE)
(43)	CHILD SEAT	(90)	SPARE TIRE
	INTERIOR LOOSE OBJECT	(96)	
		1	
(32)		(97)	EJECTED, UNKNOWN CONTACT
(52)	INTERNAL FLYING GLASS (FROM ANY SOURCE)	(96)	IMPACT FORCE, "WHIPLASH",
	•	(55)	
(41)	· · · · · · · · · · · · · · · · · · ·	(00)	HYPEREXTENSION/COMPRESSION
(41)	•		



### INJURY CLASSIFICATION IC-4

# CODES FOR OCCUPANT INJURY CLASSIFICATION (OIC)

•		
ł	DODY	REGION
	HUIDY	HE GILLIN

- (H) HEAD/SKULL
- (F) FACE
- (N) NECK
- (S) SHOULDER
- (X) UPPER EXTREMITIES
- (A) ARM (UPPER)
- (E) ELBOW
- (R) FOREARM
- (W) WRIST/HAND
- (C) CHEST
- (M) ABDOMEN
- (B) BACK
- (P) PELVIC/HIP
- (Y) LOWER EXTREMITIES
- (T) THIGH
- (K) KNEE
- (L) LEG (LOWER)
- (Q) ANKLE/FOOT
- (O) WHOLE BODY
- (U) UNKNOWN

# 3 LESION

- (L) LACERATION
- (C) CONTUSION
- (A) ABRASION
- (F) FRACTURE
- (P) PERFORATION, PUNCTURE
- (K) CONCUSSION
- (V) AVULSION
- (R) RUPTURE
- (S) SPRAIN
- (D) DISLOCATION
- (N) CRUSH
- (M) AMPUTATION
- (B) BURN
- (G) DETACHMENT, SEPARATION
- (Z) FRACTURE AND DISLOCATION
- (T) STRAIN
- (E) TOTAL SEVERANCE, TRANSECTION
- (O) OTHER
- (U) UNKNOWN

# 4 SYSTEMORGAN

- (S) SKELETAL
- (V) VERTEBRAE
- (J) JOINTS
- (D) DIGESTIVE
- (L) LIVER
- (N) NERVOUS SYSTEM
- (B) BRAIN
- (C) SPINAL CORD
- (E) EARS
- (O) EYES
- (A) ARTERIES
- (H) HEART
- (Q) SPLEEN
- (G) UROGENITAL
- (K) KIDNEYS
- (R) RESPIRATORY
- (P) PULMONARY/LUNGS
- (M) MUSCLES
- (T) THYROID, OTHER ENDOCRINE GLAND
- (I) INTEGUMENTARY (SKIN)
- (W) ALL SYSTEMS IN REGION
- (U) UNKNOWN

# 2 ASPECT

- (R) RIGHT
- (L) LEFT
- (B) BILATERAL
- (C) CENTRAL
- (A) ANTERIOR/FRONT
- (P) POSTERIOR/BACK
- (S) SUPERIOR/UPPER
- (I) INFERIOR/LOWER
- (W) WHOLE REGION
- (U) UNKNOWN

# SEVERITY 5 SYSTEMIORGAN 4 LESION 5 ASPECT 0 BODY REGION 1

### 5 SEVERITY (OR 'AIS', ABBREVIATED INJURY SCALE)

- (0) NONE
- (1) MINOR
- (2) MODERATE
- (3) SERIOUS
- (4) SEVERE
- (5) CRITICAL
- (6) MAXIMUM
- (9) UNKNOWN













31-98 #6













31-98 #1















































